CATEGORY 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9901280108 DOC.DATE: 99/01/21 NOTARIZED: NO DOCKET #
FACIL:50-270 Oconee Nuclear Station, Unit 2, Duke Power Co. 05000270
AUTH.NAME AUTHOR AFFILIATION
MCCOLLUM,W.R Duke Power Co.
RECIP.NAME RECIPIENT AFFILIATION
Records Management Branch (Document Control Desk)

SUBJECT: Forwards LER 96-007-02,concerning technical inoperability of LPIS for App R scenario.Corrective actions to prevent inadequate work practice root caused have been completed.

DISTRIBUTION CODE: IE22T COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 2+7
TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR	COPIES ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR	COPIES ENCL
	PD2-2 PD	1	1	LABARGE,D	1	1
INTERNAL:	ACRS	1	1	AEOD/SPD/RAB	2	2
	AEOD/SPD/RRAB	1	1	FILE CENTER	1	1
	NRR/DE/ECGB	1	1	NRR/DE/EELB	1	1
	NRR/DE/EMEB	1	1	NRR/DRCH/HICB	1	1
	NRR/DRCH/HOHB	1	1	NRR/DRCH/HQMB	1	1
	NRR/DRPM/PECB	1	1	NRR/DSSA/SPLB	1	1
	RES/DET/EIB	1	1	RGN2 FILE 01	1	1
EXTERNAL:	L ST LOBBY WARD	1	1	LITCO BRYCE,J H	1	1
	NOAC POORE,W.	1	1	NOAC QUEENER,DS	1	1
	NRC PDR	1	1	NUDOCS FULL TXT	1	1

C A T E G O R Y 1 D O C U M E N T

NOTE TO ALL "RIDS" RECIPIENTS:
PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED
TOTAL NUMBER OF COPIES REQUIRED: LTTR 23 ENCL 23

Duke Energy

W. R. McCollum, Jr.
Vice President

Duke Energy Corporation
Oconee Nuclear Station
P.O. Box 1439
Seneca, SC 29679
(864) 885-3107 OFFICE
(864) 885-3564 FAX

January 21, 1999

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Subject: Oconee Nuclear Station
Docket Nos. 50-269, -270, -287
Licensee Event Report 270/96-07, Revision 2
Problem Investigation Process No.: 3-096-2566

Gentlemen:

Pursuant to 10 CFR 50.73 Sections (a) (1) and (d), attached is Licensee Event Report 270/96-07 Revision 2, concerning the technical inoperability of the Low Pressure Injection System for an Appendix R Scenario.

A Planned Corrective Action to perform a one time test to verify proper operation of the Appendix R Damage Repair Valve Control Panel was submitted in Revision 1 of this report. The proper wiring configuration has been verified to match the as-built design documents. Since the one time test will not provide any additional information related to the acceptability of the current wiring configurations, it is not necessary. The corrective actions to prevent the inadequate work practice root cause have been completed.

Revision 2 to this report is being submitted in accordance with 10 CFR 50.73 (a) (2) (v) (B). This event is considered to be of no significance with respect to the health and safety of the public.

Very truly yours,

W. R. McCollum, Jr.

IE22

Attachment

9901280108 990121
PDR ADOCK 05000270
S PDR

cc: Mr. Luis A. Reyes
Administrator, Region II
U.S. Nuclear Regulatory Commission
61 Forsyth Street, S. W., Suite 23T85
Atlanta, GA 30303

Mr. D. E. LaBarge
U.S. Nuclear Regulatory Commission
Office of Nuclear Reactor Regulation
Washington, D.C. 20555

INPO Records Center
700 Galleria Parkway
Atlanta, GA 30339-5957

Mr. M. A. Scott
NRC Resident Inspector
Oconee Nuclear Station