Hammond?

Hill, Carol

From: Alan Heltemes <aheltemes@Sanjel.com>
Sent: Tuesday, March 01, 2016 3:38 PM
To: Hill, Carol
Cc: Tony McCullough
Subject: [External_Sender] FW: Sanjel NRC License 05-29427-01
Attachments: NRC Application for Amendment 8-21-2015.pdf; US Leak Tests.zip

Hello Carol

In follow-up to our recent phone call please see the following e-mail as well as the attached documents as per Michelle's request.

If possible, can you provide me with an ETA on when we can expect to see a copy of our amended license?

Regards

Alan

PUBLIC
☐ Immediate Release
☑ Normal Release

NON-PUBLIC
☐ A.3 Sensitive-Security Related
☐ A.7 Sensitive Internal
☐ Other:

Reviewer: MRL Date: 4/4/16

From: Alan Heltemes
Sent: Thursday, December 17, 2015 2:09 PM
To: michellehammond@nrc.gov
Cc: Tony McCullough
Subject: Sanjel NRC License 05-29427-01

Hello Michelle

In follow-up to our recent phone call regarding errors in our license 05-29427-05 amendment 04. Please find the attached request for amendment dated Aug 21, 2015, where-by Sanjel is requesting the license condition 17A mentioned in our call. As discussed, Michael Pankey is no longer employed by Sanjel and there-for needs to have his name removed from this license condition. Sanjel's preference would be to amend this condition to the wording inside the parenthesis in the attached request dated Aug 21, 2015.

Also as mentioned in our recent conversation, please remove the Billings, MT location from our license as this facility has been closed and was only used as a temporary storage while maintenance was being completed on the assigned unit. As this facility was only a maintenance facility and no gauges were ever used or assigned to this location. I have attached the most recent copies of our leak tests as per your request.

Thank you for your time and attention, it was a pleasure speak with you today.

Let me know of any questions or concerns

Happy Holidays

Alan Heltemes
HSE- Advisor

Sanjel (USA) Inc.
511 22nd Ave N.E.

590530

Williston, N.D. 58801
P: 701-774-8699
C: 701-339-2800
F: 701-774-8809
www.sanjel.com

Sanjel

33 Years of Pride. Est. 1982

Before printing this e-mail, think if it is necessary

This message may be subject to legal privilege and/or agreement(s) of confidentiality so please restrict its use and distribution accordingly. If you are not the intended rec
the error and delete this e-mail from your system. The contents of any email correspondence to or from Sanjel may be subject to review in accordance with Sanjel's Priva
Telecommunication policies. ©2014 Sanjel. All rights reserved.

№ 590530

Sanjel Sanjel (USA) Inc. 511 - 16th Street, Suite 300, Denver, CO 80202 | 303.893.6866 | 303.893.6854

August 21, 2015

United States Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 400
Arlington, TX 76001-8064

RE: Request for Amendment of License 05-29427-01

Dear Sir or Madam:

Sanjel Inc. has made a number of changes to our business recently that necessitate changes to our radioactive materials license. As a result, Sanjel is requesting three amendments to our License #05-29427-01.

First, please amend Sections 1 and 2 to reflect the new address for Sanjel Corporation to the following:

Sanjel Corporation
Sanjel Limited Partnership
Dba Sanjel (USA) Inc.
1630 Welton Street
Suite 300 & Suite 400
Denver, CO 80202

Second, in Section 10, please remove Chinook, MT and Riverton, WY. These offices have been closed and all radioactive material has been removed. Attached are copies of leak tests for the equipment that was assigned to these locations prior to closure.

Finally, Sanjel is requesting that condition 17A be amended to "Installation, initial radiation surveys, alignment, relocation and removal from service shall be performed by persons who have received the training described in application dated April 29, 2011, and letters dated August 16, 2011 and September 5, 2011, and are authorized by the RSO, or by persons specifically licensed by the U.S. Nuclear Regulatory Commission or an Agreement State to perform such services."

Thank you for your time and attention to these changes.

Sincerely,

V. Alan Heltemes
Radiation Safety Officer
Sanjel USA Inc
511 22nd Ave NE
Williston, ND 58801
(701)774-8699 – Office
(701)339-2800 – Cell
(701)774-8809 – Fax
aheltemes@sanjel.com

590530

BETWEEN:

Accounts Receivable/Payable
and
Regional Licensing Branches

[FOR ARPB USE]
INFORMATION FROM WBL

Program Code: 03120
Status Code: Pending Amendment
Fee Category: 3P
Exp. Date:
Fee Comments:
Decom Fin Assur Reqd: N

License Fee Worksheet - License Fee Transmittal

A. REGION

1. APPLICATION ATTACHED

Applicant/Licensee:	Sanjel USA, Inc.
Received Date:	03/01/2016
Docket Number:	3038472
Mail Control Number:	590530
License Number:	05-29427-01
Action Type:	Amendment

2. FEE ATTACHED

Amount: _____

Check No.: _____

3. COMMENTS

Signed: Carol L Hice

Date: 3/31/16

B. LICENSE FEE MANAGEMENT BRANCH (Check when milestone 03 is entered / /)

1. Fee Category and Amount: _____

2. Correct Fee Paid. Application may be processed for:

Amendment: _____

Renewal: _____

License: _____

3. OTHER_____

_____

Signed: _____

Date: _____