REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8411010395 DOC.DATE: 84/10/23 NOTARIZED: NO DOCKET #
FACIL:50-244 Robert Emmet Ginna Nuclear Plant, Unit 1, Rochester G 05000244
AUTH.NAME AUTHOR AFFILIATION
KOBER,R.W. Rochester Gas & Electric Corp.
RECIP.NAME RECIPIENT AFFILIATION
PAULSON,W.A. Operating Reactors Branch 5

SUBJECT: Advises that per 840924 meeting w/NRC & US Tool & Die re revised seismic analysis of 840402 submittal,spent fuel storage Rack 5 weld orientations inspected & verified as consistent w/calculations in 840927 ltr.

DISTRIBUTION CODE: A001D COPIES RECEIVED:LTR 1 ENCL 0 SIZE: 1
TITLE: OR Submittal: General Distribution

NOTES:NRR/DL/SEP 1cy. 05000244
OL:09/19/69

	RECIPIENT ID CODE/NAME		COPIES LTTR	COPIES ENCL	RECIPIENT ID CODE/NAME		COPIES LTTR	COPIES ENCL
	NRR ORB5 BC	01	7	7				
INTERNAL:	ADM/LFMB		1	0	ELD/HDS4		1	0
	NRR/DE/MTEB		1	1	NRR/DL DIR		1	1
	NRR/DL/ORAB		1	0	NRR/DSI/METB		1	1
	NRR/DSI/RAB		1	1	REG FILE	04	1	1
	RGN1		1	1				
EXTERNAL:	ACRS	09	6	6	LPDR	03	1	1
	NRC PDR	02	1	1	NSIC	05	1	1
	NTIS		1	1				
NOTES:			1	1				

TOTAL NUMBER OF COPIES REQUIRED: LTTR 27 ENCL 24 0

ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649-0001

ROGER W. KOBER
VICE PRESIDENT
ELECTRIC & STEAM PRODUCTION

TELEPHONE
AREA CODE 716 546-2700

October 23, 1984

Director of Nuclear Reactor Regulation
Attention: Mr. Walter A. Paulson, Acting Chief
Operating Reactors Branch No. 5
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Subject: Modification of Spent Fuel Storage Racks
R. E. Ginna Nuclear Power Plant
Docket No. 50-244

Dear Mr. Paulson:

On September 24, 1984 members of the NRC staff met with representatives of Rochester Gas and Electric Corporation and its contractor U. S. Tool and Die to discuss the revised seismic analysis for our submittal of April 2, 1984.

During this meeting we agreed to verify the weld orientation in the racks when a rack was removed from the pool. On October 22, 1984 Mr. John Cook (RG&E) and Mr. Dale Michel (USTD) inspected Rack 5 and verified that the orientation of the welds in the rack was consistent with that indicated on Figure 5.2.1 of the mechanical analysis attached to our September 27, 1984 letter. This orientation was used in the calculations.

Very truly yours,

Roger W. Kober

Roger W. Kober

A001
1/0