REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8205040419 DOC.DATE: 82/04/26 NOTARIZED: NO DOCKET #
FACIL:50-244 Robert Emmet Ginna Nuclear Plant, Unit 1, Rochester G 05000244
AUTH.NAME AUTHOR AFFILIATION
MAIER,J.E. Rochester Gas & Electric Corp.
RECIP.NAME RECIPIENT AFFILIATION
CRUTCHFIELD,D. Operating Reactors Branch 5

SUBJECT: Forwards Suppl to Section 6.4 to "Affect of Thermal Transient on RCS Steam Generator Tube Rupture Incident," suppl. SEE REPTS. #8205040422

DISTRIBUTION CODE: ZZZZS COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 1+40
TITLE: * * * * * * S P E C I A L D I S T R I B U T I O N C O D E * * * *

NOTES:NRR/DL/SEP 1cy. 05000244

RECIPIENT ID CODE/NAME	COPIES LTTR	COPIES ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR	COPIES ENCL

SEE ATTACHMENT FOR Distribution.

TOTAL NUMBER OF COPIES REQUIRED: LTTR 40 ENCL 40

ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649

JOHN E. MAIER
Vice President

TELEPHONE
AREA CODE 716 546-2700

April 26, 1982

RECEIVED
MAY 3 1982
US NUCLEAR REGULATORY COMMISSION
DOCUMENT MANAGEMENT BR
TIDC

Director of Nuclear Reactor Regulation
Attention: Mr. Dennis M. Crutchfield, Chief
Operating Reactors Branch No. 5
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Subject: Incident Evaluation
Steam Generator Tube Rupture Incident
R. E. Ginna Nuclear Power Plant
Docket No. 50-244

Dear Mr. Crutchfield:

This letter is in response to requests from members of the NRC Staff for information to supplement our Incident Evaluation Report, which was submitted by letter dated April 13, 1982. Attachment A supplements Section 6.4, Thermal Transient on Reactor Coolant System.

Very truly yours,

John E. Maier

Attachment

2222
s
1/1

8205040419 820426
PDR ADOCK 05000244
P PDR