REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8703160201 DOC. DATE: 87/03/06 NOTARIZED: NO DOCKET #
FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251
AUTH. NAME AUTHOR AFFILIATION
WOODY, C. O. Florida Power & Light Co.
RECIP. NAME RECIPIENT AFFILIATION
Document Control Branch (Document Control Desk)

SUBJECT: Special rept: nonfunctional fire barrier pentration not returned to functional status within 7 days. Caused by incomplete App R alternate shutdown work. Compensatory measurements continuing. List of breached barriers encl.

DISTRIBUTION CODE: A006D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 5
TITLE: OR/Licensing Submittal: Fire Protection

NOTES:

	RECIPIENT ID CODE/NAME		COPIES LTTR	COPIES ENCL	RECIPIENT ID CODE/NAME		COPIES LTTR	COPIES ENCL
	PWR-A PD2 LA		1	0	PWR-A PD2 PD 04		5	5
	McDONALD, D		1	1	PWR-A PSB		1	1
INTERNAL:	ADM/LFMB		1	0	IE WHITNEY, L		1	1
	NRR STANG, J	07	2	2	NRR WERMEIL, J06		1	0
	OGC/HDS2		1	0	REG FILE	01	1	1
EXTERNAL:	LPDR	03	1	1	NRC PDR	02	1	1
	NSIC	05	1	1				

TOTAL NUMBER OF COPIES REQUIRED: LTTR 18 ENCL 14

P. O. BOX [illegible]00, JUNO BEACH, FL 33408-0420

FPL

MARCH 06 1987
L-87-110

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Gentlemen:

Re: Turkey Point Units 3 and 4
Docket Nos. 50-250 and 50-251
Special Report - Breached Fire Barriers

In accordance with Technical Specification 6.9.3 the attached Special Report is provided for your information.

Should there be any questions on this information, please contact us.

Very truly yours,

C. O. Woody
Group Vice President
Nuclear Energy

COW/RG/gp

Attachment

cc: Dr. J. Nelson Grace, Regional Administrator, Region II, USNRC
Senior Resident Inspector, USNRC, Turkey Point Plant

A006
1/1

SPECIAL REPORT

MARCH 6, 1987

FIRE BARRIERS BREACHED FOR LONGER THAN SEVEN DAYS

Purpose:

Technical Specification 3.14.5.b requires the submission of a report to the NRC if a non-functional fire barrier penetration is not returned to functional status within 7 days. In accordance with the above requirement, this special report on the breached barriers is being generated in order to notify the NRC. This report will be updated on a 30 day basis until the Appendix R associated work is complete.

Event:

The plant has been and is continuing to implement numerous modifications, mainly in accordance with Appendix R Alternate Shutdown requirements. The schedular exemptions for the Safe Shutdown modifications, which outlined the alternative compensatory measures to be taken when a barrier is breached, expired on September 30, 1986, and on October 1, 1986. Upon the expiration of the exemptions, the compensatory measures as described in Attachment 1 of our letter L-85-386 (dated October 11, 1985), are continuing to be in place until the Safe Shutdown modifications are complete. Breaches incurred during Alternate Shutdown modifications are governed by the Technical Specifications or the exemptions, as applicable.

Cause and Corrective Actions:

The major cause of the breached barriers is the Appendix R Alternate Shutdown work which remains to be completed. Due to the large volume of work being performed, the plant is reporting the breaches in this one report, rather than on a case-by-case basis. The breaches reported this month are breaches which are either open or closed, but were open for longer than 7 days (see attached list of breached barriers).

The plant continues to implement the compensatory measures as applicable.

TURKEY POINT PLANT - NUCLEAR
IMPAIRMENT CONTROL SYSTEM - 1986
FILE:ICS86.WK1
REV DATE: 03/03/87

IMPAIRMENT NUMBER	REQUEST NO.	DESCRIPTION	OPEN DATE	CLOSING DATE
	86-0280	RACEWAY PROTECTION NO:B-3J1712-4"	12/18/86	02/04/87

NOTE: BREACHES TO FIRE BARRIERS CLOSED IN FEBRUARY, BUT WERE OPENED FOR MORE THAN 7 DAYS.

TURKEY POINT PLANT - NUCLEAR
IMPAIRMENT CONTROL SYSTEM - 1987
FILE:ICS87.WK1
REV DATE: 03/03/87

IMPAIRMENT NUMBER	REQUEST NO.	DESCRIPTION	OPEN DATE	CLOSING DATE
	87-0028	STRUCTURAL STEEL FIREPROOFING MEMBER:W14X30	01/08/87	02/05/87
	87-0065	FIRE BARRIERS NO:070N-E023	01/19/87	02/06/87
	87-0066	FIRE BARRIERS NO:070N-E035	01/19/87	02/06/87
	87-0067	FIRE BARRIERS NO:098N-E043	01/19/87	02/06/87
	87-0069	FIRE BARRIERS NO:070E-E009	01/19/87	02/10/87
	87-0071	FIRE BARRIERS NO:098E-E034	01/19/87	02/10/87
	87-0073	FIRE BARRIERS NO:041E-E003	01/19/87	02/13/87

NOTE: BREACHES TO FIRE BARRIERS CLOSED IN FEBRUARY, BUT WERE OPENED FOR MORE THAN 7 DAYS.

TURKEY POINT PLANT - NUCLEAR
IMPAIRMENT CONTROL SYSTEM - 1987
FILE:ICS87.WK1
REV DATE: 03/03/87

IMPAIRMENT NUMBER	REQUEST NO.	DESCRIPTION	OPEN DATE	CLOSING DATE
1038		PENETRATION DISCREPANCY PER NCR 87-0022	02/05/87	
1039		PENETRATION DISCREPANCY PER NCR 87-0022	02/05/87	
1041		PENETRATION DISCREPANCY PER NCR 87-0022	02/05/87	
1051		FIRE DOORS NO:101.1	02/10/87	
1034		FIRE DAMPER 72A	01/28/87	