(7-77)

LICENSEE EVENT REPORT

POOR ORIGINAL

CONTROL BLOCK: [ ] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[ ] [GAEIH2] (2) [00-000000-00] (3) [4] [1111] (4) [ ] (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

[01] REPORT SOURCE [L] (6) [05000363] (7) [091279] (8) [091979] (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

[02] During Startup operations, the hydrogen gas concentration increased greater than T. S.
[03] Appendix B Section 2.1.3.h limit of 4%. Hydrogen concentration exceeded 4% for approx-
[04] imately 18 minutes. On 9-15-79 at 1391 MWE preheater problems caused hydrogen to ex-
[05] ceed 4 % for approximately 30 minutes. This is a repetitive occurrence as reported
[06] on LER 79-78. There were no effects upon the public health and safety due to these
[07] events.
[08]

[09] SYSTEM CODE [MB] (11) CAUSE CODE [B] (12) CAUSE SUBCODE [A] (13) COMPONENT CODE [REC OMB] (14) COMP. SUBCODE [Z] (15) VALVE SUBCODE [Z] (16)

(17) LER RO REPORT NUMBER: EVENT YEAR [79] SEQUENTIAL REPORT NO. [095] OCCURRENCE CODE [03] REPORT TYPE [L] REVISION NO. [0]

ACTION TAKEN [G] (18) FUTURE ACTION [F] (19) EFFECT ON PLANT [Z] (20) SHUTDOWN METHOD [Z] (21) HOURS (22) [0000] ATTACHMENT SUBMITTED [ ] (23) NPRD-4 FORM SUB. [N] (24) PRIME COMP. SUPPLIER [N] (25) COMPONENT MANUFACTURER [C116] (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

[16] The probable cause for the event on 9-12-79 is that while preheating Offgas lines
[11] moisture entered the Recombiner thus reducing its recombining capability. The
[12] probable cause for the event on 9-15-79 is that preheater temperature was not
[13] sufficient to prevent moisture from entering Recombiner and reduced its recombining
[14] capability. Swapped preheaters and recombiners to correct problem.

[15] FACILITY STATUS [C] (28) % POWER [012] (29) OTHER STATUS (30) NA METHOD OF DISCOVERY [A] (31) DISCOVERY DESCRIPTION (32) Plant Personnel Observation

[16] ACTIVITY RELEASED [Z] (33) ACTIVITY CONTENT OF RELEASE [Z] (34) AMOUNT OF ACTIVITY (35) NA LOCATION OF RELEASE (36) NA

[17] PERSONNEL EXPOSURES NUMBER [000] (37) TYPE [Z] (38) DESCRIPTION (39) NA

[18] PERSONNEL INJURIES NUMBER [000] (40) DESCRIPTION (41) NA

[19] LOSS OF OR DAMAGE TO FACILITY (42) TYPE [Z] DESCRIPTION NA

7909280364

[20] PUBLICITY ISSUED [N] (44) DESCRIPTION (45) NA

1036 090

NRC USE ONLY

NAME OF PREPARER S. X. Baxley, Supt. of Operations PHONE: (912) 367-6686