LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | M D C C N 1 (2) C [illegible] - 0 0 0 0 0 - 0 0 (3) 4 1 1 1 1 (4) (5)

7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T

0 1 | REPORT SOURCE L (6) 0 5 0 0 0 3 1 7 (7) 1 0 0 6 7 9 (8) 1 0 0 8 7 9 (9)

7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During a routine trip recovery the reactor was made critical at 1525. At

0 3 | 1600 while the senior control room operator was reviewing the outside operator's

0 4 | log, he noticed that intake structure doors IS1 and and IS2 were logged open

0 5 | (T.S.3.0.3 and 3.7.10). The doors were immediately shut and locked. This is

0 6 | not a repetitive occurrence.

0 7 |

0 8 | 80

7 8 9

	SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
0 9	Z Z (11)	A (12)	X (13)	Z Z Z Z Z Z (14)	Z (15)	Z (16)

7 8 9 10 11 12 13 18 19 20

(17) LER RO REPORT NUMBER: EVENT YEAR 7 9 (21 22) — (23) SEQUENTIAL REPORT NO. 0 5 7 (24 26) / (27) OCCURRENCE CODE 0 1 (28 29) REPORT TYPE X (30) — (31) REVISION NO. 0 (32)

	ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS (22)	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
	X (18)	X (19)	Z (20)	Z (21)	0 0 0 0	N (23)	N (24)	A (25)	Z 9 9 9 (26)

33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | This event was caused by failure of security personnel to notify the Shift

1 1 | Supervisor of their intent to open water tight doors for maintenance access.

1 2 | Immediate corrective action was to shut and lock the doors. Further corrective

1 3 | action will be detailed in the follow-up report.

1 4 |

7 8 9 80

FACILITY STATUS C (28) | % POWER 0 0 5 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY A (31) Log review | DISCOVERY DESCRIPTION (32)

1 5 | 7 8 9 10 12 13 44 45 46 80

ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

1 6 | 7 8 9 10 11 44 45 80

PERSONNEL EXPOSURES NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) NA

1 7 | 7 8 9 11 12 13 80

PERSONNEL INJURIES NUMBER 0 0 0 (40) | DESCRIPTION (41) NA

1 8 | 7 8 9 11 12 80

1130 078

LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) | DESCRIPTION (43) NA

1 9 | 7 8 9 10 80

7910110405

PUBLICITY ISSUED N (44) | DESCRIPTION (45) NA

2 0 | 7 8 9 10 68 69 80

NRC USE ONLY

NAME OF PREPARER S. M. Davis PHONE (301) 234-7942