POOR ORIGINAL

NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | ARAN01 (2) | 00-000-00 (3) | 4 1111 (4) | (5)
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T
01 | REPORT SOURCE L (6) | 050003 13 (7) | 10 08 79 (8) | 11 07 79 (9)
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During the Quarterly Surveillance Test (10-7-79), CV1616, the sodium
03 hydroxide tank discharge valve failed in the ES position. This was re-
04 paired and the redundant valve, CV1617, was proved operable. Later, CV
05 1616 was found to have no control board indication and was declared in-
06 operable per T.S.3.3.4.(D). Unit power operation was continued per T.S.3.
07 3.5. Occurrence was reportable per T.S.12.3.2(b). There have been no
08 similar occurrences.

09 | SYSTEM CODE SA (11) | CAUSE CODE A (12) | CAUSE SUBCODE C (13) | COMPONENT CODE ZZZZZZ (14) | COMP SUBCODE Z (15) | VALVE SUBCODE Z (16)
7 8 9 10 11 12 13 18 19 20

(17) LER/RO REPORT NUMBER | EVENT YEAR 79 | — | SEQUENTIAL REPORT NO. 018 | / | OCCURRENCE CODE 03 | REPORT TYPE L | — | REVISION NO 0
21 22 23 24 26 27 28 29 30 31 32

ACTION TAKEN B (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS 0000 (22) | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB Y (24) | PRIME COMP SUPPLIER Z (25) | COMPONENT MANUFACTURER Z999 (26)
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The control fuse was found blown in the breaker cubicle. This was caused
11 by a control wire being pinched and grounded to the operator cover. The
12 control wire was reinsulated and the control fuse was replaced. Craft
13 personnel were cautioned to check carefully in order to avoid this type
14 of failure.

15 | FACILITY STATUS E (28) | % POWER 100 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY B (31) | DISCOVERY DESCRIPTION (32) Routine Shift Check
7 8 9 10 12 13 44 45 46 80

16 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA
7 8 9 10 11 44 45 80

PERSONNEL EXPOSURES
17 | NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) NA
7 8 9 11 12 13 80

PERSONNEL INJURIES
18 | NUMBER 000 (40) | DESCRIPTION (41) NA
7 8 9 11 12 80

LOSS OF OR DAMAGE TO FACILITY (43)
19 | TYPE Z (42) | DESCRIPTION NA
7 8 9 10 80

PUBLICITY
20 | ISSUED N (44) | DESCRIPTION (45) NA
7 8 9 10 68 80

1399 114

NRC USE ONLY
69 80

NAME OF PREPARER Lindsley S. Bramlett PHONE: 501-968-2519

7911270 330