(7 77)

LICENSEE EVENT REPORT

CONTROL BLOCK: [ ] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | M A P P S 1 (2) | 0 0 0 0 0 0 0 0 0 0 0 (3) | 4 1 1 1 1 (4) | (5)

LICENSEE CODE | LICENSE NUMBER | LICENSE TYPE | CAT

CON'T

0 1 | REPORT SOURCE L (6) | 0 5 0 - 0 2 9 3 (7) | 0 7 1 3 7 9 (8) | 0 7 1 9 7 9 (9)

DOCKET NUMBER | EVENT DATE | REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | On July 13, 1979, Pilgrim Station was notified by its Engineering Department

0 3 | that while continuing its evaluation of seismic restraints per I&E Bulletin

0 4 | 79-02, it was discovered that two pipe supports did not meet the original

0 5 | design SSE specifications. These supports are on the HPCI test line down-

0 6 | stream of the test valve and on the RHR crosstie.

0 7 |

0 8 |

0 9 | SYSTEM CODE S F (11) | CAUSE CODE B (12) | CAUSE SUBCODE A (13) | COMPONENT CODE S U P O R T (14) | COMP. SUBCODE B (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 7 9 | — | SEQUENTIAL REPORT NO. 0 2 2 | / | OCCURRENCE CODE 0 1 | REPORT TYPE T | — | REVISION NO. 0

ACTION TAKEN F (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD (21) | HOURS (22) 0 0 0 0 | ATTACHMENT SUBMITTED N (23) | NPE-0-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER A (25) | COMPONENT MANUFACTURER X 9 9 9 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | This situation was caused by a design error. The pipe supports were modified

1 1 | under a Plant Design Change Request (PDCR), and are now within the safety

1 2 | factor requirements.

1 3 |

1 4 |

1 5 | FACILITY STATUS G (28) | % POWER 0 0 0 (29) | OTHER STATUS (30) N/A | METHOD OF DISCOVERY C (31) | DISCOVERY DESCRIPTION (32) Engineering Evaluation

1 6 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) N/A | LOCATION OF RELEASE (36) N/A

PERSONNEL EXPOSURES

1 7 | NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) N/A

PERSONNEL INJURIES

1 8 | NUMBER 0 0 0 (40) | DESCRIPTION (41) N/A

LOSS OF OR DAMAGE TO FACILITY

1 9 | TYPE Z (42) | DESCRIPTION N/A

7907260745 S

454 241

PUBLICITY

2 0 | ISSUED N (44) | DESCRIPTION (45) N/A | NRC USE ONLY

NAME OF PREPARER John M. Fulton PHONE (617) 746-7900

GPO 917-926