C FORM 366 (7) U.S. NUCLEAR REGULATORY COMMISSION

Unit 2

LICENSEE EVENT REPORT

Report No. 2-79-35/1T-0

CONTROL BLOCK: (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 | P A P B S 2 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | (5)

8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

1 | REPORT SOURCE: L (6) | 0 5 0 - 0 2 7 7 (7) | 0 7 0 6 7 9 (8) | 0 7 2 0 7 9 (9)

8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

2 | Inspection program performed in response to IE Bulletin 79-02 identified

3 | 18 shell type anchors which failed to torque properly. These anchors are

4 | associated with the emergency cooling water piping supports. The piping

5 | is only used in unusual events such as flood and loss of Conowingo Pond.

6 | It is unlikely that piping integrity could be affected by these anchor

7 | test failures. Safety significance is therefore minimal.

8 |

8 9 80

9 | SYSTEM CODE: S H (11) | CAUSE CODE: B (12) | CAUSE SUBCODE: C (13) | COMPONENT CODE: S U P O R T (14) | COMP. SUBCODE: B (15) | VALVE SUBCODE: Z (16)

8 9 10 11 12 13 18 19 20

(17) LER/RO REPORT NUMBER: EVENT YEAR 7 9 (21 22) | — (23) | SEQUENTIAL REPORT NO. 0 3 5 (24 26) | / (27) | OCCURRENCE CODE 0 1 (28 29) | REPORT TYPE T (30) | — (31) | REVISION NO. 0 (32)

ACTION TAKEN: A (18) | FUTURE ACTION: Z (19) | EFFECT ON PLANT: Z (20) | SHUTDOWN METHOD: Z (21) | HOURS (22): 0 0 0 0 | ATTACHMENT SUBMITTED: Y (23) | NPRD-4 FORM SUB.: N (24) | PRIME COMP. SUPPLIER: Z (25) | COMPONENT MANUFACTURER: I 2 0 9 (26)

33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | Anchors were incorrectly installed in the grout beneath the support

11 | plate instead of the structural concrete. All test failed anchors were

12 | properly replaced and successfully tested by 7/10/79.

13 |

14 |

8 9 80

15 | FACILITY STATUS: E (28) | % POWER: 1 0 0 (29) | OTHER STATUS (30): U/3 at 98% | METHOD OF DISCOVERY: D (31) | DISCOVERY DESCRIPTION (32): Work on IE Bulletin 79-02

8 9 10 12 13 44 45 46 80

16 | ACTIVITY RELEASED: Z (33) | CONTENT OF RELEASE: Z (34) | AMOUNT OF ACTIVITY (35): N/A | LOCATION OF RELEASE (36): N/A

8 9 10 11 44 45 80

17 | PERSONNEL EXPOSURES: NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39): N/A

8 9 11 12 13 80

543 245

18 | PERSONNEL INJURIES: NUMBER 0 0 0 (40) | DESCRIPTION (41): N/A

8 9 11 12 80

19 | LOSS OF OR DAMAGE TO FACILITY: TYPE Z (42) | DESCRIPTION: N/A

8 9 10 80

7908010 546 S

20 | PUBLICITY: ISSUED N (44) | DESCRIPTION (45): N/A | NRC USE ONLY

8 9 10 68 69 80

NAME OF PREPARER: M. J. Cooney PHONE: (215) 841-5020

GPO 917-226