U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: | | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 | G | A | E | I | H | 2 | (2) | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | (3) | 4 | 1 | 1 | 1 | 1 | (4) | | | (5)
LICENSEE CODE 14 — LICENSE NUMBER 25 — LICENSE TYPE 30 — 57 CAT 58

REPORT SOURCE | L | (6) | 0 | 5 | 0 | 0 | 0 | 3 | 6 | 6 | (7) | 0 | 7 | 0 | 1 | 7 | 9 | (8) | 0 | 7 | 1 | 3 | 7 | 9 | (9)
60 — 61 DOCKET NUMBER 68 — 69 EVENT DATE 74 — 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

While performing MSIV closure startup test HNP-2-10925 on 2-14-79, RCIC was initiated on low water level following reactor scram and isolated before injecting to the vessel. No manual start was subsequently made. There were no personnel injuries or radiation exposures as a result of this incident nor were there any effects to public health and safety.

SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
C E (11)	X (12)	X (13)	Z Z Z Z Z Z (14)	Z (15)	Z (16)

(17) LER RO REPORT NUMBER: EVENT YEAR 7 9 — SEQUENTIAL REPORT NO. 0 6 4 — OCCURRENCE CODE 0 3 — REPORT TYPE L — REVISION NO. 0

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS (22)	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
Z (18)	Z (19)	Z (20)	Z (21)	0 0 0 0	N (23)	N (24)	Z (25)	Z 9 9 9 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

No investigation of the cause of the isolation was made because no action was initiated. Reportable Occurrence Report No. 50-366/1979-46 identifies an RCIC turbine trip on high exhaust line pressure on 6-3-79 due to a failed checkvalve. This is the suspected cause of isolation on 2-14-79. See R. O. 50-366/1979-46 for corrective action.

FACILITY STATUS	% POWER	OTHER STATUS (30)	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
B (28)	0 0 0 (29)	N/A	A (31)	Operator Observation

ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)
Z (33)	Z (34)	N/A	N/A

PERSONNEL EXPOSURES

NUMBER	TYPE	DESCRIPTION (39)
0 0 0 (37)	Z (38)	N/A

PERSONNEL INJURIES

NUMBER	DESCRIPTION (41)
0 0 0 (40)	N/A

LOSS OF OR DAMAGE TO FACILITY (43)

TYPE	DESCRIPTION
Z (42)	N/A

PUBLICITY

ISSUED	DESCRIPTION (45)
N (44)	N/A

79072 3·0553

359 189

NRC USE ONLY

NAME OF PREPARER T. V. Greene, Supt. Plt. Eng. Serv. PHONE: 912-367-7781