NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | ILQAD1 (2) | 000-000-000 (3) | 4111 (4) | (5)
LICENSEE CODE | LICENSE NUMBER | LICENSE TYPE | CAT

CON'T
01 | REPORT SOURCE L (6) | 05000254 (7) | 062279 (8) | 071379 (9)
DOCKET NUMBER | EVENT DATE | REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 After returning the Unit One Diesel Generator to service, following the monthly
03 preventive maintenance inspection, a fuel line leak was discovered which required
04 additional servicing. To make a proper repair, the Unit One diesel had to be taken
05 out of service from 9:40 a.m. to 12:20 p.m. The 1/2 diesel generator had been proven
06 operable prior to taking the Unit One diesel out of service and the surveillance
07 requirements of T.S.3.9.E.1 were started.
08

09 SYSTEM CODE EE (11) | CAUSE CODE E (12) | CAUSE SUBCODE B (13) | COMPONENT CODE ENGINE (14) | COMP. SUBCODE D (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 79 | — | SEQUENTIAL REPORT NO. 022 | / | OCCURRENCE CODE 03 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN B (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0000 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER N (25) | COMPONENT MANUFACTURER G100 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The cause of the leak was a worn gasket on the fuel line filter. The filter gasket
11 was replaced and the diesel operability surveillance was subsequently performed.
12
13
14

15 FACILITY STATUS E (28) | % POWER 097 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY B (31) | DISCOVERY DESCRIPTION (32) Routine test and inspection

16 ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

PERSONNEL EXPOSURES
17 NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) NA

PERSONNEL INJURIES
18 NUMBER 000 (40) | DESCRIPTION (41) NA

LOSS OF OR DAMAGE TO FACILITY (43)
19 TYPE Z (42) | DESCRIPTION NA

7907250378
407 222

PUBLICITY
20 ISSUED N (44) | DESCRIPTION (45) NA

NRC USE ONLY

NAME OF PREPARER J. Vahrenwald PHONE 309-654-2241 Ext. 195