NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

LER 79-25/1P

CONTROL BLOCK: | | | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

Line	Field	Value
01	Licensee Code (2)	V T V Y S 1
01	License Number (3)	0 0 - 0 0 0 0 0 - 0 0
01	License Type (4)	4 1 1 1 1
01	CAT (5)	
CON'T 01	Report Source (6)	L
01	Docket Number (7)	0 5 0 0 0 2 7 1
01	Event Date (8)	1 0 0 3 7 9
01	Report Date (9)	1 0 0 3 7 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

While performing refuel outage associated inspection of 8x8R fuel assemblies, evidence of end plug wear was discovered on the water rods associated with both assemblies. Examination of fuel rods located in the general area of the water rods revealed no indication of end plug wear.

System Code (11)	Cause Code (12)	Cause Subcode (13)	Component Code (14)	Comp. Subcode (15)	Valve Subcode (16)
R C	E	B	F U E L X X	Z	Z

LER/RO REPORT NUMBER (17)

Event Year		Sequential Report No.		Occurrence Code	Report Type		Revision No.
7 9	—	0 2 5	/	0 1	P	—	0

Action Taken (18)	Future Action (19)	Effect on Plant (20)	Shutdown Method (21)	Hours (22)	Attachment Submitted (23)	NPRD-4 Form Sub. (24)	Prime Comp. Supplier (25)	Component Manufacturer (26)
Z	Z	Z	Z	0 0 0 0	N	Y	Y	G 0 8 0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

The cause of the wear is unknown at present. An evaluation will be made, along with corrective action if deemed necessary in a subsequent report.

Facility Status (28)	% Power (29)	Other Status (30)	Method of Discovery (31)	Discovery Description (32)
H	0 0 0	NA	C	Fuel Assembly Inspection

Activity Released (33)	Content of Release (34)	Amount of Activity (35)	Location of Release (36)
Z	Z	NA	NA

PERSONNEL EXPOSURES

Number (37)	Type (38)	Description (39)
0 0 0		NA

PERSONNEL INJURIES

Number (40)	Description (41)
0 0 0	NA

1076 087

LOSS OF OR DAMAGE TO FACILITY (43)

Type (42)	Description
Z	NA

7910110308

PUBLICITY

Issued (44)	Description (45)	NRC USE ONLY
N	NA	

NAME OF PREPARER W. F. Conway

PHONE: 802-257-7711

GPO 917-926