NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | C O F S V 1 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 2 0 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T
01 | REPORT SOURCE L (6) | 0 5 0 0 0 2 6 7 (7) | 1 1 0 7 7 9 (8) | 1 2 0 6 7 9 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 At 1326 hours on November 7, 1979, with the reactor in a shutdown condition, the line
03 supplying backup bearing water to 1A helium circulator was determined to be impaired
04 due to an impaired hanger 10A-H-21208. This is a degraded mode of LCO 4.3.10 and is
05 reportable per Fort St. Vrain Technical Specification AC 7.5.2(b)2. No affect on
06 health and safety of the public.
07
08

09 SYSTEM CODE C B (11) | CAUSE CODE B (12) | CAUSE SUBCODE A (13) | COMPONENT CODE S U P O R T (14) | COMP. SUBCODE A (15) | VALVE SUBCODE Z (16)

(17) LER RO REPORT NUMBER: EVENT YEAR 7 9 | — | SEQUENTIAL REPORT NO. 0 5 8 | / | OCCURRENCE CODE 0 3 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN A (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0 0 0 0 | ATTACHMENT SUBMITTED Y (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER A (25) | COMPONENT MANUFACTURER X 9 9 9 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Cause of hanger 10A-H-21208 and system impairment was a missing anchor bolt and
11 stripped anchor bolt shield. Missing bolt and defective shield were replaced and
12 hanger verified operable.
13
14

15 FACILITY STATUS D (28) | % POWER 0 0 0 (29) | OTHER STATUS (30) N/A | METHOD OF DISCOVERY C (31) | DISCOVERY DESCRIPTION (32) Engineering Analysis of Hangers

16 ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) N/A | LOCATION OF RELEASE (36) N/A

PERSONNEL EXPOSURES
17 NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) N/A

PERSONNEL INJURIES
18 NUMBER 0 0 0 (40) | DESCRIPTION (41) N/A

LOSS OF OR DAMAGE TO FACILITY (43)
19 TYPE Z (42) | DESCRIPTION N/A

PUBLICITY
20 ISSUED N (44) | DESCRIPTION (45) N/A

1541 355

7912120336

NRC USE ONLY

NAME OF PREPARER J. W. Gahm PHONE: (303) 785-2253