Update Report - Previous Report Date September 12, 1979

NRC FORM 366
(7-77)

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | ARAN02 (2) | 00-0000-00 (3) | 4111 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T
01 | REPORT SOURCE L (6) | 05000368 (7) | 082279 (8) | 102579 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During Mode 1 operation, the data link from CEAC #1 to the "B" CPC
03 dropped a bit causing an inaccurate output indication, resulting in the
04 "B" CPC channel tripping. The data link failed in the conservative
05 direction and the remaining CEAC data links were operable.
06 There have been no similar occurrences.
07 Reportable per T.S. 6.9.1.9b.
08

09 SYSTEM CODE IA (11) | CAUSE CODE E (12) | CAUSE SUBCODE E (13) | COMPONENT CODE INSTRU (14) | COMP. SUBCODE Y (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 79 | — | SEQUENTIAL REPORT NO. 075 | / | OCCURRENCE CODE 03 | REPORT TYPE X | — | REVISION NO. 1

ACTION TAKEN A (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS 0000 (22) | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB N (24) | PRIME COMP SUPPLIER N (25) | COMPONENT MANUFACTURER S525 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The data link output error was caused by a failed optical amplifier. The
11 data link was repaired and the "B" CPC returned to service within one
12 hour meeting the requirements of Action Statement T.S. Table 3.3-1,
13 Action 2a.
14

15 FACILITY STATUS B (28) | % POWER 030 (29) | OTHER STATUS (30) Pwr Escalation Test | METHOD OF DISCOVERY A (31) | DISCOVERY DESCRIPTION (32) n/a

16 ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) n/a | LOCATION OF RELEASE (36) n/a

17 PERSONNEL EXPOSURES NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) n/a

18 PERSONNEL INJURIES NUMBER 000 (40) | DESCRIPTION (41) na/

19 LOSS OF OR DAMAGE TO FACILITY (43) TYPE Z (42) | DESCRIPTION n/a

20 PUBLICITY ISSUED N (44) | DESCRIPTION (45) n/a

NRC USE ONLY

NAME OF PREPARER Rex Pendergraft PHONE (501) 968-2519

12 4 198

7910310 424