NRC FORM 366
(7-77)

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | A R A N 0 2 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T
01 | REPORT SOURCE L (6) | 0 5 0 0 0 3 6 8 (7) | 0 9 2 6 7 9 (8) | 1 0 2 5 7 9 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During mode 2 operation, Rod #46 dropped 4 times to the lower electrical
03 limit. With CEA #46 misaligned by more than 19 inches from the group
04 average position, operation in mode 2 continued per T.S. Action Statement
05 3.1.3.1(c). There have been no similar occurrences.
06 Reportable per T.S. 6.9.1.9 b.
07
08

09 SYSTEM CODE R D (11) | CAUSE CODE E (12) | CAUSE SUBCODE B (13) | COMPONENT CODE C R D R V E (14) | COMP SUBCODE Z (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 7 9 | — | SEQUENTIAL REPORT NO. 0 8 3 | / | OCCURRENCE CODE 0 3 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN A (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0 0 0 0 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER N (25) | COMPONENT MANUFACTURER C 4 9 0 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Investigation did not reveal cause for rod drops. The voltage to the
11 CEDM gripper coils was increased and the rod was exercised successfully.
12 The CEA was realigned within 1 hour per Action Statement 3.1.3.1(c).
13
14

15 FACILITY STATUS B (28) | % POWER 0 0 0 (29) | OTHER STATUS (30) Pwr Escalation | METHOD OF DISCOVERY A (31) | DISCOVERY DESCRIPTION (32) n/a

16 ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) n/a | LOCATION OF RELEASE (36) n/a

17 PERSONNEL EXPOSURES NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) n/a

18 PERSONNEL INJURIES NUMBER 0 0 0 (40) | DESCRIPTION (41) n/a

19 LOSS OF OR DAMAGE TO FACILITY (43) TYPE Z (42) | DESCRIPTION n/a

20 PUBLICITY ISSUED N (44) | DESCRIPTION (45) n/a | NRC USE ONLY

NAME OF PREPARER Rex Pendergraft PHONE (501) 968-2519

12 4 199

7910310 428