LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | M D C C N 2 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | (5)

7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T

0 1 | REPORT SOURCE L (6) | 0 5 0 0 0 3 1 8 (7) | 0 5 2 0 7 9 (8) | 0 5 2 5 7 9 (9)

7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | At 1142 while inserting group 5 control element assemblies (CEA's), CEA 36

0 3 | dropped to the bottom of the core. In accordance with T.S. 3.1.3.1.f,

0 4 | reactor power was reduced to less than 70% at 1222. At 1242 CEA 36 was

0 5 | withdrawn and realigned with its group. LER 78-48 (U-1) and 79-12 (U-2)

0 6 | describe similar events.

0 7 |

0 8 | 7 8 9 80

0 9 | SYSTEM CODE R B (11) | CAUSE CODE E (12) | CAUSE SUBCODE A (13) | COMPONENT CODE C R D R V E (14) | COMP. SUBCODE Z (15) | VALVE SUBCODE Z (16)

7 8 9 10 11 12 13 18 19 20

(17) LER/RO REPORT NUMBER: EVENT YEAR 7 9 (21 22) | — (23) | SEQUENTIAL REPORT NO. 0 1 6 (24 26) | / (27) | OCCURRENCE CODE 0 3 (28 29) | REPORT TYPE L (30) | — (31) | REVISION NO. 0 (32)

ACTION TAKEN Z (18) | FUTURE ACTION F (19) | EFFECT ON PLANT B (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0 0 0 5 (33 34 35 36 37 40) | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER N (25) | COMPONENT MANUFACTURER P 3 1 4 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The dropped rod is assumed to be the result of a spike in the 15 volt power

1 1 | supply. A design modification to improve the reliability of the system by

1 2 | installing dual power supplies (FCR 78-72) is to be installed during the

1 3 | next refueling outage.

1 4 | 7 8 9 80

1 5 | FACILITY STATUS E (28) | % POWER 1 0 0 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY A (31) | DISCOVERY DESCRIPTION (32) Operator Observation

7 8 9 10 12 13 44 45 46 80

1 6 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

7 8 9 10 11 44 45 80

PERSONNEL EXPOSURES

1 7 | NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) NA 2268 268

7 8 9 11 12 13 80

PERSONNEL INJURIES

1 8 | NUMBER 0 0 0 (40) | DESCRIPTION (41) NA

7 8 9 11 12 80

LOSS OF OR DAMAGE TO FACILITY (43)

1 9 | TYPE Z (42) | DESCRIPTION NA 7906010207 S

7 8 9 10 80

PUBLICITY

2 0 | ISSUED N (44) | DESCRIPTION (45) NA | NRC USE ONLY

7 8 9 10 68 69 80

NAME OF PREPARER S. M. Davis/M. J. Miernicki PHONE (301) 234-7942/7962

NRC FORM 366 (7-77)