LICENSEE EVENT REPORT

CONTROL BLOCK: | | | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

Line	Field	Value
0 1	LICENSEE CODE (9–14)	A L J M F 2 (2)
	LICENSE NUMBER (15–25)	0 0 - 0 0 0 0 0 - 0 0 (3)
	LICENSE TYPE (26–30)	4 1 1 1 1 (4)
	CAT (57–58)	(5)
CON'T	REPORT SOURCE (60)	L (6)
	DOCKET NUMBER (61–68)	0 5 0 0 0 3 6 4 (7)
	EVENT DATE (69–74)	0 6 0 2 8 1 (8)
	REPORT DATE (75–80)	0 6 2 4 8 1 (9)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 At 1430 on 6/2/81, while performing FNP-2-STP-213.4B (Steam Generator 2C FT-495 Loop
0 3 Calibration). The FT495 instrumentation loop was declared inoperable when it failed to
0 4 meet the surveillance test voltage requirements. Tech. Spec. 3.3.1, in part, requires
0 5 the FT495 instrumentation loop to be operable. Tech. Spec. 3.3.1 action statement
0 6 requirements were met. Health/safety of the public was not affected.
0 7
0 8

0 9	SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
	I A (11)	E (12)	G (13)	I N S T R U (14)	T (15)	Z (16)

(17) LER/RO REPORT NUMBER

EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE	REPORT TYPE		REVISION NO.
8 1	—	0 1 8	/	0 3	L	—	0

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS (22)	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
A (18)	Z (19)	Z (20)	Z (21)	0 0 0 0	N (23)	N (24)	N (25)	W 1 2 0 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Investigation of the out of Spec. voltage condition revealed a faulty comparator card.
1 1 The card was replaced and following the successful completion of the calibration proce-
1 2 dure, instrumentation loop FT495 was returned to service at 1530 on 6/2/81.
1 3
1 4

1 5	FACILITY STATUS	% POWER	OTHER STATUS (30)	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
	E (28)	0 3 2 (29)	NA	B (31)	Surveillance Test

1 6	ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)
	Z (33)	Z (34)	NA	NA

PERSONNEL EXPOSURES

1 7	NUMBER	TYPE	DESCRIPTION (39)
	0 0 0 (37)	Z (38)	NA

PERSONNEL INJURIES

1 8	NUMBER	DESCRIPTION (41)
	0 0 0 (40)	NA

LOSS OF OR DAMAGE TO FACILITY (43)

1 9	TYPE	DESCRIPTION
	Z (42)	NA

POOR ORIGINAL

PUBLICITY

2 0	ISSUED	DESCRIPTION (45)	NRC USE ONLY
	N (44)	NA	

8106300249

W. G. Hairston, III (205)899-5156