NRC FORM 366 (7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | SCNEE1 (2) | 00-00000-00 (3) | 4 | 1111 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T
01 | REPORT SOURCE L (6) | 05000269 (7) | 021281 (8) | 031381 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 On February 12, 1981, the level indication for the EWST was declared inoperable
03 when the control room indicator showed 0% water level. During this incident,
04 the EWST was verified full by use of the Heise Gauge in the turbine building.
05 Also both HPSW pumps were manually operable. Thus, this incident was of no
06 significance with respect to safe operation, and the health and safety of the
07 public were not affected.
08

09 SYSTEM CODE WA (11) | CAUSE CODE E (12) | CAUSE SUBCODE B (13) | COMPONENT CODE BLOWER (14) | COMP. SUBCODE Z (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 81 — SEQUENTIAL REPORT NO. 004 — OCCURRENCE CODE 03 — REPORT TYPE L — REVISION NO. 0

ACTION TAKEN B (18) | FUTURE ACTION X (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS 0000 (22) | ATTACHMENT SUBMITTED Y (23) | NPRD-4 FORM SUB. Y (24) | PRIME COMP. SUPPLIER L (25) | COMPONENT MANUFACTURER X999 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The primary cause was loose connectors on the air compressor starter terminals.
11 A second significant cause was the sticking valves for the area evacuation
12 horn. All connections on the motor starter were tightened. All solenoid
13 valves for the area evacuation horn were replaced. Improvements will be made
14 to help reduce the potential for future occurrences.

FACILITY STATUS G (28) | % POWER 000 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY A (31) | DISCOVERY DESCRIPTION (32) Operator observation

ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

PERSONNEL EXPOSURES — NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) NA

PERSONNEL INJURIES — NUMBER 000 (40) | DESCRIPTION (41) NA

LOSS OF OR DAMAGE TO FACILITY (43) — TYPE Z (42) | DESCRIPTION NA

PUBLICITY — ISSUED N (44) | DESCRIPTION (45) NA | NRC USE ONLY

NAME OF PREPARER J. L. Jones PHONE: (704) 373-8197

8107010337

5