NRC FORM 366
(7-77)

U.S. NUCLEAR REGULATORY COMMISSION

# LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: [ ] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | ARAN01 (2) | 00-000-00 (3) | 4 | 1111 (4) | [ ] (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T
01 | REPORT SOURCE L (6) | 050003 13 (7) | 04 08 81 (8) | 05 05 81 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | Immediately following a plant trip, the steam driven Emergency Feedwater
03 | (EFW) Pump, P7A, was started and then was tripped by the turbine overspeed
04 | mechanism. The electric driven EFW pump remained operable. The EFW
05 | turbine trip mechanism was reset and the pump was successfully put into
06 | service. Similar to LER 50-313/80-021. Reportable per T.S. 6.12.3.2.b.
07 |
08 |

09 | SYSTEM CODE CH (11) | CAUSE CODE E (12) | CAUSE SUBCODE B (13) | COMPONENT CODE TURBIN (14) | COMP. SUBCODE Z (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 81 — SEQUENTIAL REPORT NO. 005 — OCCURRENCE CODE 03 — REPORT TYPE L — REVISION NO. 0

ACTION TAKEN E (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS 0000 (22) | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB Y (24) | PRIME COMP. SUPPLIER A (25) | COMPONENT MANUFACTURER T147 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | The cause of the EFW turbine driver trip was determined to be due to worn
11 | edges on the trip mechanism. The mechanism would trip when mechanical
12 | vibrations occurred during startup. The mechanism was adjusted to latch
13 | firmly. The preventive maintenance program was revised to include the
14 | latch mechanism inspection.

15 | FACILITY STATUS X (28) | % POWER 000 (29) | OTHER STATUS (30) Plant trip | METHOD OF DISCOVERY A (31) | DISCOVERY DESCRIPTION (32) Operator Observation

16 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

17 | PERSONNEL EXPOSURES NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) NA

18 | PERSONNEL INJURIES NUMBER 000 (40) | DESCRIPTION (41) NA

19 | LOSS OF OR DAMAGE TO FACILITY (43) TYPE Z (42) | DESCRIPTION NA

20 | PUBLICITY ISSUED N (44) | DESCRIPTION (45) NA | NRC USE ONLY

NAME OF PREPARER Chris N. Shively PHONE: 501/968-2519

8105080300