(7-77)

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1	LICENSEE CODE: N J O C P 1 (2) · LICENSE NUMBER: 0 0 - 0 0 0 0 0 - 0 0 (3) · LICENSE TYPE: 4 1 1 1 1 (4) · CAT (5)
CON'T 0 1	REPORT SOURCE: L (6) · DOCKET NUMBER: 0 5 0 0 0 2 1 9 (7) · EVENT DATE: 0 6 0 3 8 1 (8) · REPORT DATE: 0 7 0 1 8 1 (9)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 On June 3, 81 while performing monthly surveillance testing of high

0 3 pressure sensors RE03B, C & D were found to be less conservative than

0 4 specified in the Technical Specification. The safety significance is

0 5 considered minimal since these switches would have actuated but at a

0 6 pressure 8 pounds higher (worst case) than the Technical Specification

0 7 limit.

0 8

	SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
0 9	I B (11)	X (12)	Z (13)	I N S T R U (14)	S (15)	Z (16)

(17) LER/RO REPORT NUMBER	EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE	REPORT TYPE		REVISION NO.
	8 1	—	0 2 1	/	0 3	L	—	0

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS (22)	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
E (18)	Z (19)	Z (20)	Z (21)	0 0 0 0	Y (23)	Y (24)	X (25)	B 0 6 9 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause of switches RE03BCD tripping within eight pounds of setpoint

1 1 is attributed to sensor repeatability. The pressure switches were reset

1 2 to trip within the prescribed limit. The long [illegible] solution will be the

1 3 replacement of the RE03 pressure switches with a[illegible] trip system

1 4 during our upcoming refueling outage.

	FACILITY STATUS	% POWER	OTHER STATUS (30)	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
1 5	H (28)	0 7 8 (29)	NA	(31)	Monthly Surveillance Test

	ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)
1 6	Z (33)	Z (34)	NA	NA

PERSONNEL EXPOSURES

	NUMBER	TYPE	DESCRIPTION (39)
1 7	0 0 0 (37)	B (38)	NA

PERSONNEL INJURIES

	NUMBER	DESCRIPTION (41)
1 8	0 0 0 (40)	NA

LOSS OF OR DAMAGE TO FACILITY (43)

	TYPE	DESCRIPTION
1 9	Z (42)	NA

PUBLICITY

	ISSUED	DESCRIPTION (45)	NRC USE ONLY
2 0	N (44)	NA	

8107130301 810701
PDR ADOCK 05000219
S PDR

NAME OF PREPARER Edward I. Riggle PHONE (609) 693-6985