REVISED REPORT - PREVIOUS REPORT DATE 5-27-81

NRC FORM 366 (7 77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | ARAN02 (2) | 00-000-00 (3) | 4 1 1 1 1 (4) | (5)

LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T

01 | REPORT SOURCE L (6) | 0 5 0 0 0 3 6 8 (7) | 0 5 0 6 8 1 (8) | 0 6 2 6 8 1 (9)

DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During Mode 6 operation, Emergency Diesel Generator (EDG) #2 received a
03 generator lockout during the load rejection test portion of the 18 month
04 surveillance. This is a non-valid failure as defined by Reg. Guide 1.108,
05 Rev. 1, Position C.2.e(2), as the anti-motoring relay is by-passed on a
06 SIAS signal. There has been one failure in the last 100 valid tests. The
07 redundant EDG and offsite power was available meeting requirements of
08 T.S. 3.8.1.2. Similar to LER 50-368/81-016. Reportable per T.S. 4.8.1.1.3
09 pursuant to T.S. 6.9.1.9.b.

09 | SYSTEM CODE EE (11) | CAUSE CODE E (12) | CAUSE SUBCODE A (13) | COMPONENT CODE RELAYX (14) | COMP SUBCODE D (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 81 | SEQUENTIAL REPORT NO. 018 | OCCURRENCE CODE 03 | REPORT TYPE X | REVISION NO. 1

ACTION TAKEN E (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0000 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB Y (24) | PRIME COMP. SUPPLIER A (25) | COMPONENT MANUFACTURER G080 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 This anti-motoring relay holding coil adjustment was found to be out of
11 tolerance. This adjustment is normally considered to be a "factory setting".
12 Adjustments were made and EDG load rejection test successfully completed.
13 The procedure was revised to include relay checks. Similar relays on
14 EDG #1 and Main Generator are being checked utilizing revised procedure.

15 | FACILITY STATUS H (28) | % POWER 000 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY B (31) | DISCOVERY DESCRIPTION (32) Surveillance Testing

16 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

PERSONNEL EXPOSURES

17 | NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) NA

PERSONNEL INJURIES

18 | NUMBER 000 (40) | DESCRIPTION (41) NA

LOSS OF OR DAMAGE TO FACILITY (43)

19 | TYPE Z (42) | DESCRIPTION NA

PUBLICITY

20 | ISSUED N (44) | DESCRIPTION (45) NA | NRC USE ONLY

NAME OF PREPARER Chris N. Shively PHONE: 501/968-2519

8107280526