NRC FORM 366
(7-77)

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | NJSGS2 (7) | 00-000-00 (3) | 41111 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T 01 | REPORT SOURCE L (6) | 05000311 (7) | 072781 (8) | 082481 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 On July 27, 1981, during check source testing, the containment atmosphere particulate
03 radioactivity monitoring detector 2R11A was found to be out of specification. 2R11A
04 was declared inoperable, and action statements 3.3.3.1, action 24 and 3.4.7.1.a
05 were entered at 0920 hours, July 27, 1981.
06
07
08

09 SYSTEM CODE MC (11) | CAUSE CODE C (12) | CAUSE SUBCODE Z (13) | COMPONENT CODE INSTRU (14) | COMP SUBCODE E (15) | VALVE SUBCODE Z (16)

(17) LER RO REPORT NUMBER: EVENT YEAR 81 | — | SEQUENTIAL REPORT NO 075 | / | OCCURRENCE CODE 03 | REPORT TYPE L | — | REVISION NO 0

ACTION TAKEN B (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS 0000 (22) | ATTACHMENT SUBMITTED Y (23) | NPRD-4 FORM SUB N (24) | PRIME COMP SUPPLIER L (25) | COMPONENT MANUFACTURER V115 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The cause of the out of specification test results was the detector was approximately
11 one-half inch back from its' proper position in the lead pig. The detector was
12 repositioned approximately one-half inch forward in the pig. The high voltage and
13 discriminator voltage was reset. The detector was tested satisfactorily and
14 returned to service. Action statements 3.3.3.1, action 24 and 3.4.7.1.a were
terminated 1530 hours, July 27, 1981.

15 FACILITY STATUS E (28) | % POWER 048 (29) | OTHER STATUS (30) N/A | METHOD OF DISCOVERY B (31) | DISCOVERY DESCRIPTION (32) Check source testing.

16 ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

PERSONNEL EXPOSURES
17 NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) NA

PERSONNEL INJURIES
18 NUMBER 000 (40) | DESCRIPTION (41) NA

LOSS OF OR DAMAGE TO FACILITY (43)
19 TYPE Z (42) | DESCRIPTION NA

PUBLICITY
20 ISSUED N (44) | DESCRIPTION (45) NA

NRC USE ONLY

8109030227 810824
PDR ADOCK 05000311
S PDR

Frank Dickey — PHONE 609-935-5100