NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | N C M G S 1 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T
01 | REPORT SOURCE L (6) | 0 5 0 0 0 3 6 9 (7) | 0 7 2 5 8 1 (8) | 0 8 2 4 8 1 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 While in Mode 3, two steam generator feedwater containment isolation valves
03 were declared inoperable (one on 7/25/81, another on 7/26/81) in order to re-
04 pair nitrogen leaks from the tanks and valves, and recharge the nitrogen accum-
05 ulators. This violates T.S. 3.6.3. which is reportable per T.S. 6.9.1.13(b)
06 and is similar to previous R.O. #369/81-54. Since the valves were closed in
07 order to maintain containment integrity before work on them was begun, the
08 health and safety of the public were not affected.

09 SYSTEM CODE C H (11) | CAUSE CODE E (12) | CAUSE SUBCODE E (13) | COMPONENT CODE V A L V O P (14) | COMP SUBCODE C (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 8 1 | — | SEQUENTIAL REPORT NO. 1 2 4 | / | OCCURRENCE CODE 0 3 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN F (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS 0 0 0 0 (22) | ATTACHMENT SUBMITTED Y (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER L (25) | COMPONENT MANUFACTURER B 3 5 0 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The N_2 Accumulators of both valves were losing pressure due to leaks around the
11 fittings which appear to be the result of having been tightened too many times.
12 The pressure regulator, associated gauges, and tubing of 4 feedwater system
13 valves were relocated downstream of the external filter mounted on the valve
14 operator base plate, and Parker fittings on the N_2 Accumulator lines were re-
placed with socket weld fittings.

FACILITY STATUS X (28) | % POWER 0 0 0 (29) | OTHER STATUS (30) Mode 3 | METHOD OF DISCOVERY B (31) | DISCOVERY DESCRIPTION (32) Routine surveillance

15

ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) N/A | LOCATION OF RELEASE (36) N/A

16

PERSONNEL EXPOSURES
NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) N/A

17

PERSONNEL INJURIES
NUMBER 0 0 0 (40) | DESCRIPTION (41) N/A

18

LOSS OF OR DAMAGE TO FACILITY (43)
TYPE Z (42) | DESCRIPTION N/A

19

PUBLICITY
ISSUED N (44) | DESCRIPTION (45) N/A | NRC USE ONLY

20

NAME OF PREPARER Phillip B. Nardoci PHONE: (704) 373-7432

8109080283 810824
PDR ADOCK 05000369
S PDR