NRC FORM 366 (7-77) U.S. NUCLEAR REGULATORY COMMISSION

# LICENSEE EVENT REPORT

CONTROL BLOCK: [ ] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 | W I K N P 1 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT 58

CON'T
2 | REPORT SOURCE L (6) | 0 5 0 0 0 3 0 5 (7) | 0 8 0 7 8 1 (8) | 0 8 2 8 8 1 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

3 | Surveillance testing during steady state operation indicated that one containment
4 | pressure transmitter was out of calibration such that the SI high containment pressure
5 | set point was less conservative than required by Tech. Specs. The remaining two
6 | channels of containment pressure instrumentation were in calibration, therefore, the
7 | 2/3 logic would have responded as designed. There was no effect on plant operation
8 | or public safety.
9 |

SYSTEM CODE: I B (11) | CAUSE CODE: X (12) | CAUSE SUBCODE: Z (13) | COMPONENT CODE: I N S T R U (14) | COMP. SUBCODE: T (15) | VALVE SUBCODE: Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 8 1 (21 22) — SEQUENTIAL REPORT NO. 0 2 5 (24 26) — OCCURRENCE CODE 0 3 (29 30) — REPORT TYPE L (30) — REVISION NO. 0 (32)

ACTION TAKEN: E (18) | FUTURE ACTION: Z (19) | EFFECT ON PLANT: Z (20) | SHUTDOWN METHOD: Z (21) | HOURS (22): 0 0 0 0 | ATTACHMENT SUBMITTED: N (23) | NPRD-4 FORM SUB.: N (24) | PRIME COMP. SUPPLIER: N (25) | COMPONENT MANUFACTURER: F 1 8 0 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | The cause of this incident was attributed to instrument drift of the Foxboro
11 | pressure transmitter. The transmitter was recalibrated and returned to service.
12 | No further action is required.
13 |
14 |

FACILITY STATUS: E (28) | % POWER: 1 0 0 (29) | OTHER STATUS (30): NA | METHOD OF DISCOVERY: B (31) | DISCOVERY DESCRIPTION (32): Surveillance Test

ACTIVITY RELEASED: Z (33) | CONTENT OF RELEASE: Z (34) | AMOUNT OF ACTIVITY (35): NA | LOCATION OF RELEASE (36): NA

PERSONNEL EXPOSURES
NUMBER: 0 0 0 (37) | TYPE: Z (38) | DESCRIPTION (39): NA

PERSONNEL INJURIES
NUMBER: 0 0 0 (40) | DESCRIPTION (41): NA

LOSS OF OR DAMAGE TO FACILITY (43)
TYPE: Z (42) | DESCRIPTION: NA

PUBLICITY
ISSUED: N (44) | DESCRIPTION (45): NA

8109100059 810831
PDR ADOCK 05000305
S PDR

NRC USE ONLY

NAME OF PREPARER: P.M. Lindberg — PHONE: (414) 388-2560