western union

Telegram

50-255

312 -
CS
812

328p

TO:U S NUCLEAR REGULATORY COMMISSION
FROM:R M KRICH

TO: U S NUCLEAR REGULATORY COMMISSION
ATTN: PALISADES PLANT SECTION CHIEF
799 ROOSEVELT AVENUE
GLEN ELLYN, ILLINOIS

W.U. 1201-SF (R5-69)

western union

Telegram

FROM: R M KRICH, PALISADES

CC: VICE-PRESIDENT, NUCLEAR OPERATIONS, P-26-(17B)
NUCLEAR LICENSING ADMINISTRATOR, P-24-314B

THIS CONFIRMS PROMPT NOTIFICATION OF AN OCCURRENCE REPORTABLE PER TS 6.9.2.a(2). ON AUGUST 1, 1983, AT 2052, WITH THE C-BIB SAFETY INJECTION (SI) TANK INOPERABLE DUE TO ROUTINE SAMPLING, AN ADDITIONAL
SI TANK, T-82A, BECAME INOPERABLE DUE TO LOW LEVEL. THIS OCCURRENCE OF TWO INOPERABLE SI TANKS AT THE SAME TIME LASTED FOR APPROXIMATELY 4 MINUTES AT WHICH TIME T-82A WAS RESTORED TO OPERABILITY PER TS 3.3 .2.

INITIAL REPORT WAS MADE VIA THE NRC HOT LINE AT 2140 ON AUGUST 1, 1983. NOTIFICATION TO THE NRC RESIDENT INSPECTOR WAS MADE ON AUGUST

8308100124 830802
PDR ADOCK 05000255
S PDR

AUG 5 1983

W.U. 1201-SF (R5-69)