NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | NYJAF1 (2) | 00-00000-000 (3) | 4 | 1111 (4) | (5)
LICENSEE CODE (9–14) | LICENSE NUMBER (15–25) | LICENSE TYPE (26–30) | CAT (57–58)

CON'T
01 | REPORT SOURCE L (6) | 05000333 (7) | 083082 (8) | 091082 (9)
DOCKET NUMBER (60–68) | EVENT DATE (69–74) | REPORT DATE (75–80)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During the performance of a surveillance test, an operator pulled the
03 wrong fuses such that a later step caused both Standby Liquid Control
04 System squib valves to be actuated. The system was de-energized, pro-
05 tectively tagged and declared inoperable while the firing circuits were
06 repaired (TS 3.4.a). The event did not have any safety consequences as
07 the system was still operable until protectively tagged for repair. The
08 system could have been restored in a short period of time during repair.

09 | SYSTEM CODE PC (11) | CAUSE CODE A (12) | CAUSE SUBCODE B (13) | COMPONENT CODE VALVOP (14) | COMP. SUBCODE H (15) | VALVE SUBCODE D (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 82 | — | SEQUENTIAL REPORT NO. 041 | / | OCCURRENCE CODE 03 | REPORT TYPE X | — | REVISION NO. 1

ACTION TAKEN H (18) | FUTURE ACTION G (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0000 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER N (25) | COMPONENT MANUFACTURER C151 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The proper fuses were clearly designated in the surveillance test.
11 The operator went to the wrong fuse board in the correct panel. The
12 operator was counselled regarding this action. This LER and the
13 lesson learned will be included in the Training Program for all
14 operators.

15 | FACILITY STATUS E (28) | % POWER 099 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY B (31) | DISCOVERY DESCRIPTION (32) Operator Observation

16 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

17 | PERSONNEL EXPOSURES NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) NA

18 | PERSONNEL INJURIES NUMBER 000 (40) | DESCRIPTION (41) NA

8209210209

19 | LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) | DESCRIPTION (43) NA

20 | PUBLICITY ISSUED N (44) | DESCRIPTION (45) NA | NRC USE ONLY

NAME OF PREPARER _____ PHONE: _____

GPO 917-926