LICENSEE EVENT REPORT

CONTROL BLOCK: | | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | A L J M F 1 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | | (5)

LICENSEE CODE | LICENSE NUMBER | LICENSE TYPE | CAT

REPORT SOURCE L (6) | 0 5 0 0 0 3 4 8 (7) | 0 4 1 3 8 2 (8) | 0 4 3 0 8 2 (9)

DOCKET NUMBER | EVENT DATE | REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 At C404 on 4/13/82 during routine surveillance, the FI-497 (Steam Generator 1C Feedwater

0 3 Flow) instrumentation channel was declared inoperable when the maximum allowable channel

0 4 check error was exceeded. Tech. Spec. 3.3.1.1, in part, requires this instrumentation

0 5 channel to be operable. Tech. Spec. 3.3.1.1 action statement requirements were met.

0 6 Health/safety of the public was not affected.

0 7

0 8

	SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP SUBCODE	VALVE SUBCODE
0 9	I A (11)	E (12)	G (13)	I N S T R U (14)	T (15)	Z (16)

(17) LER/RO REPORT NUMBER	EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE	REPORT TYPE		REVISION NO.
	8 2	—	0 1 7	/	0 3	L	—	0

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS (22)	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
C (18)	Z (19)	Z (20)	Z (21)	0 0 0 0 0	N (23)	N (24)	A (25)	F 1 8 0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 This event was due to a faulty transmitter amplifier card. The card was replaced and

1 1 following the performance of FNP-1-STP-215.6 (Main Feedwater FT497 Loop Calibration and

1 2 Functional Test), FT497 instrumentation channel was returned to service at 1504 on 4/13/82.

1 3

1 4

	FACILITY STATUS	% POWER	OTHER STATUS (30)	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
1 5	E (28)	1 0 0 (29)	NA	B (31)	Surveillance Test

	ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)
1 6	Z (33)	Z (34)	NA	NA

PERSONNEL EXPOSURES

	NUMBER	TYPE	DESCRIPTION (39)
1 7	0 0 0 (37)	Z (38)	NA

PERSONNEL INJURIES

	NUMBER	DESCRIPTION (41)
1 8	0 0 0 (40)	NA

LOSS OF OR DAMAGE TO FACILITY (43)

	TYPE	DESCRIPTION
1 9	Z (42)	NA

PUBLICITY

	ISSUED	DESCRIPTION (45)
2 0	N (44)	NA

8205210313 820430
PDR ADOCK 05000348
S PDR

NRC USE ONLY

NAME OF PREPARER W. G. Hairston, III

PHONE: (205) 899-5156