LICENSEE EVENT REPORT

CONTROL BLOCK: [ ] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[0 1] [F L C R P 3] (3) [0 0 - 0 0 0 0 0 - 0 0] (3) [4 1 1 1 1] (4) [ ] (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T
[0 1] REPORT SOURCE [L] (6) [0 5 0 - 0 3 0 2] (7) [0 2 2 8 8 2] (8) [0 3 2 9 8 2] (9)
60 — 61 DOCKET NUMBER 68 — 69 EVENT DATE 74 — 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

[0 2] At 1800 during routine inspection, a leak was discovered on the pressure side of MUV-292
[0 3] in the "heat affected area" of the weld. This created an event contrary to T.S. 3.1.2.4.1.
[0 4] MUP-1A was secured and MUP-1C was started. Maintenance was initiated and operability was
[0 5] restored at 1800 on 3/1/82. There was no effect upon the health or safety of the general
[0 6] public. This is the first reportable occurrence for this event and this is the first
[0 7] report under this Specification.
[0 8] 7 8 9 80

[0 9] 7 8

SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
S F (11)	X (12)	Z (13)	P I P E X X (14)	A (15)	Z (16)
9 10	11	12	13 18	19	20

(17) LER/RO REPORT NUMBER: EVENT YEAR [8 2] (21 22) — [—] (23) — SEQUENTIAL REPORT NO. [0 1 3] (24 26) — [/] (27) — OCCURRENCE CODE [0 3] (28 29) — REPORT TYPE [L] (30) — [—] (31) — REVISION NO. [0] (32)

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS (22)	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
X (18)	X (19)	C (20)	Z (21)	0 0 0 8	Y (23)	N (24)	A (25)	Z 9 9 9 (26)
33	34	35	36	37 40	41	42	43	44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

[1 0] The apparent cause of this event is attributed to vibration. The weld was replaced and
[1 1] more support was added to MUV-292 to reduce vibration. Long term corrective action is
[1 2] under engineering evaluation.
[1 3]
[1 4] 7 8 9 80

FACILITY STATUS	% POWER	OTHER STATUS (30)	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
[1 5] Z (28)	0 0 0 (29)	NA	B (31)	Operator observation
7 8 9	10 12	13 44	45 46	80

ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)
[1 6] Z (33)	Z (34)	NA	NA
7 8 9	10 11	44	45 80

PERSONNEL EXPOSURES

NUMBER	TYPE	DESCRIPTION (39)
[1 7] 0 0 0 (37)	Z (38)	NA
7 8 9 11	12 13	80

PERSONNEL INJURIES

NUMBER	DESCRIPTION (41)
[1 8] 0 0 0 (40)	NA
7 8 9 11	12 80

LOSS OF OR DAMAGE TO FACILITY

TYPE	DESCRIPTION (43)
[1 9] Z (42)	NA
7 8 9	10 80

PUBLICITY

ISSUED	DESCRIPTION (45)
[2 0] N (44)	8205210420 820329 PDR ADOCK 05000302 S PDR
7 8 9	10 68 69 80

NRC USE ONLY

NAME OF PREPARER Charles G. Brown by TLS PHONE: 904/795-6486

NRC FORM 366