NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | N Y J A F 1 (2) | 0 0 - 0 0 0 0 - 0 0 0 (3) | 4 1 1 1 1 (4) | (5)

LICENSEE CODE | LICENSE NUMBER | LICENSE TYPE | CAT

CON'T

0 1 | REPORT SOURCE L (6) | 0 5 0 0 0 3 3 3 (7) | 0 3 0 9 8 2 (8) | 0 4 0 7 8 2 (9)

DOCKET NUMBER | EVENT DATE | REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During routine startup operations, following surveillance, personnel noted that

0 3 | RHR Pump C discharge check valve was not properly seating. Investigation and

0 4 | repair required that RHR Pump C be made inoperable when required by TS 3.5.A.3.

0 5 | No significant hazard existed.

0 6 |

0 7 |

0 8 |

0 9 | SYSTEM CODE C F (11) | CAUSE CODE B (12) | CAUSE SUBCODE A (13) | COMPONENT CODE V A L V E X (14) | COMP. SUBCODE C (15) | VALVE SUBCODE A (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 8 2 | — | SEQUENTIAL REPORT NO. 0 0 8 | / | OCCURRENCE CODE 0 3 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN B (18) | FUTURE ACTION X (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0 0 0 0 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. Y (24) | PRIME COMP SUPPLIER A (25) | COMPONENT MANUFACTURER P 3 0 5 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | A loose disc nut and loose disc holder allowed improper disc seating. Tightening

1 1 | of fasteners and pinning of the disc nut corrected the problem. Since the valve

1 2 | also required repair in January 1982, evaluation of possible modification

1 3 | of valve internals has been initiated.

1 4 |

1 5 | FACILITY STATUS C (28) | % POWER 0 1 2 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY A (31) | DISCOVERY DESCRIPTION (32) Operator Observation

1 6 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

1 7 | PERSONNEL EXPOSURES NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) NA

1 8 | PERSONNEL INJURIES NUMBER 0 0 0 (40) | DESCRIPTION (41) NA

1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) | DESCRIPTION (43) NA

2 0 | PUBLICITY ISSUED N (44) | DESCRIPTION (45) NA

NRC USE ONLY

8204160251 820407
PDR ADOCK 05000333
S PDR

J. Verne Childs

PHONE 315-342-3840