LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | CASO S 2 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | (5)

LICENSEE CODE | LICENSE NUMBER | LICENSE TYPE | CAT

CON'T

0 1 | REPORT SOURCE L (6) | 0 5 0 0 0 3 6 1 (7) | 0 7 0 8 8 2 (8) | 0 8 0 2 8 2 (9)

DOCKET NUMBER | EVENT DATE | REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | Emergency Chilled Water Pump P-160 which provides cooling water to Train A of the

0 3 | Control Room Emergency Air Conditioning System (E-419) could not be started

0 4 | reliably without blowing fuses. Had this system been called upon to perform its

0 5 | emergency function, the capability of maintaining Control Room air temperature

0 6 | below 110°F may have been compromised.

0 7 |

0 8 |

0 9 | SYSTEM CODE S G (11) | CAUSE CODE B (12) | CAUSE SUBCODE A (13) | COMPONENT CODE Z Z Z Z Z Z (14) | COMP. SUBCODE Z (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 8 2 | — | SEQUENTIAL REPORT NO. 0 4 3 | / | OCCURRENCE CODE 0 3 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN F (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0 0 0 0 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. N (24) | PR. ME COMP. SUPPLIER Z (25) | COMPONENT MANUFACTURER Z 9 9 9 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Fuse size specified on drawing of pump starting circuit was insufficient to carry

1 1 | maximum pump starting current. Larger fuses were installed and drawings were

1 2 | changed to specify proper size fuse.

1 3 |

1 4 |

1 5 | FACILITY STATUS B (28) | % POWER 0 0 0 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY A (31) | DISCOVERY DESCRIPTION (32) Operator observation

1 6 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36)

1 7 | PERSONNEL EXPOSURES NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) NA

1 8 | PERSONNEL INJURIES NUMBER 0 0 0 (40) | DESCRIPTION (41) NA

1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) | DESCRIPTION (43) NA

2 0 | PUBLICITY ISSUED N (44) | DESCRIPTION (45) NA

8208090216 820802
PDR ADOCK 05000361
S PDR

NRC USE ONLY

NAME OF PREPARER H. B. Ray PHONE 714/492-7700