LICENSEE EVENT REPORT

CONTROL BLOCK: [ ] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | T N S N P 1 | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | (5)
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T
01 | REPORT SOURCE L (6) | 0 5 0 0 0 3 2 7 (7) | 0 1 2 0 8 3 (8) | 0 2 1 7 8 3 (9)
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 With unit 1 in mode 3 (0% power) at 2000 CST on 01/20/83, one pressure switch for
03 the auxiliary feedwater low suction pressure actuation was declared inoperable due
04 to failure to clear alarm in the control room. This required entry into action
05 statement 20 of LCO 3.3.2.1. There was no effect upon public health and safety.
06 Previous occurrences - one (SQRO-50-327/83007).
07
08
7 8 9 80

09 SYSTEM CODE I B (11) | CAUSE CODE X (12) | CAUSE SUBCODE E (13) | COMPONENT CODE I N S T R U (14) | COMP. SUBCODE S (15) | VALVE SUBCODE Z (16)
7 8 9 10 11 12 13 18 19 20

(17) LER/RO REPORT NUMBER: EVENT YEAR 8 3 | — | SEQUENTIAL REPORT NO. 0 1 1 | / | OCCURRENCE CODE 0 3 | REPORT TYPE L | — | REVISION NO. 0
21 22 23 24 26 27 28 29 30 31 32

ACTION TAKEN X (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0 0 0 0 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER L (25) | COMPONENT MANUFACTURER D 2 4 0
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Pressure switch 1-PS-3-121A was found hanging up in the alarm state. Troubleshooting
11 revealed that the Dual Snap Model 604 pressure switch contacts would not reset. The
12 cause is unknown. Further testing did not result in any failure, and the switch
13 calibration was verified, and on 01/20/83 at 2241, the switch was returned to service.
14 No further action is planned at this time.
7 8 9 80

15 FACILITY STATUS C (28) | % POWER 0 0 0 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY B (31) | DISCOVERY DESCRIPTION (32) Operator observation
7 8 9 10 12 13 44 45 46 80

16 ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA
7 8 9 10 11 44 45 80

17 PERSONNEL EXPOSURES NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) NA
7 8 9 11 12 13 80

18 PERSONNEL INJURIES NUMBER 0 0 0 (40) | DESCRIPTION (41) NA
7 8 9 11 12 80

19 LOSS OF OR DAMAGE TO FACILITY (43) TYPE Z (42) | DESCRIPTION NA
7 8 9 10 80

8302280162 830217
PDR ADOCK 05000327
S PDR

20 PUBLICITY ISSUED N (44) | DESCRIPTION (45) NA
7 8 9 10 68 69 80

NRC USE ONLY

Name of Preparer: H. R. Rogers /M. R. Harding Phone: (615) 751-0349