NRC FORM 366 (12-81) 10 CFR 50

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

APPROVED BY OMB 3150-0011

CONTROL BLOCK: [ ] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | PASES I (2) | 00-000 00-00 (3) | 4111 1 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T

01 | REPORT SOURCE L (6) | 05000387 (7) | 031183 (8) | 040583 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 While in Operating Condition 2 (Startup) with steam dome pressure greater than
03 150psig,a technician inadvertently caused the High Pressure Coolant Injection
04 system to isolate(Technical Specification 3.5.1). The Core Spray system,Low Pres-
05 sure Coolant Injection system,Automatic Depressurization system and Reactor Core
06 Isolation Cooling system were operable. There were no consequential effects to the
07 public health and safety.
08

	SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
09	SF (11)	A (12)	C (13)	ZZZZZZ (14)	Z (15)	Z (16)

(17) LER/RO REPORT NUMBER	EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE	REPORT TYPE		REVISION NO.
	83	—	044	/	03	L	—	0

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS (22)	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER (26)
H (18)	Z (19)	Z (20)	Z (21)	0000	N (23)	N (24)	Z (25)	Z999

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 A technician was performing a monthly surveillance (SI-83-228) functional test of
11 the main steam line tunnel temperature channels. He inadvertently connected his
12 test equipment to an adjacent HPCI temperature isolation switch and brought in a
13 trip signal. HPCI was unisolated and returned to service. Personnel have been
14 counseled on the importance of proper test connections.

FACILITY STATUS	% POWER	OTHER STATUS (30)	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
15 C (28)	000 (29)	N/A	A (31)	Operator observation

ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)
16 Z (33)	Z (34)	N/A	N/A

PERSONNEL EXPOSURES NUMBER	TYPE	DESCRIPTION (39)
17 000 (37)	Z (38)	N/A

PERSONNEL INJURIES NUMBER	DESCRIPTION (41)
18 000 (40)	N/A

LOSS OF OR DAMAGE TO FACILITY TYPE	DESCRIPTION (43)
19 Z (42)	N/A

PUBLICITY ISSUED	DESCRIPTION (45)
20 N (44)	N/A

8304180361 830405
PDR ADOCK 05000387
S PDR

NRC USE ONLY

NAME OF PREPARER Jon T. Todd PHONE (717)542-2181 X3524