NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | ILDRS2 (2) | 00-00000-00 (3) | 41111 (4) | (5)
LICENSEE CODE (7–14) | LICENSE NUMBER (15–25) | LICENSE TYPE (26–30) | CAT (57–58)

CON'T
01 | REPORT SOURCE L (6) | 05000237 (7) | 032183 (8) | 041483 (9)
DOCKET NUMBER (61–68) | EVENT DATE (69–74) | REPORT DATE (75–80)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During normal Unit 3 operations, while conducting a routine inspection the
03 operator found U-2/3 diesel generator recirculating, lubricating oil pump
04 running with no pressure. U-2/3 diesel generator was declared inoperable. All
05 required surveillances were initiated and completed. Event was of minimal
06 safety significance since the normal power supply was continuously available.
07 First event of this type at Dresden.
08

09 SYSTEM CODE EE (11) | CAUSE CODE E (12) | CAUSE SUBCODE B (13) | COMPONENT CODE PUMPXX (14) | COMP SUBCODE D (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 83 | — | SEQUENTIAL REPORT NO. 021 | / | OCCURRENCE CODE 03 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN C (18) | FUTURE ACTION G (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0000 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. Y (24) | PRIME COMP. SUPPLIER N (25) | COMPONENT MANUFACTURER V125 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Event was caused by the allenscrews loosening which maintain pump internal
11 clearances(Model GB503A), resulting in a decrease in pump discharge pressure.
12 DMP 6600-4 will be changed to verify tightness of allenscrews on bearing
13 housing prior to installation. DOS 6600-1 will continue to be performed
14 to verify system operability.

15 FACILITY STATUS H (28) | % POWER 000 (29) | OTHER STATUS (30) N/A | METHOD OF DISCOVERY A (31) | DISCOVERY DESCRIPTION (32) Operator Observation

16 ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) N/A | LOCATION OF RELEASE (36) N/A

17 PERSONNEL EXPOSURES: NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) N/A

18 PERSONNEL INJURIES: NUMBER 000 (40) | DESCRIPTION (41) N/A

19 LOSS OF OR DAMAGE TO FACILITY (43): TYPE Z (42) | DESCRIPTION N/A

20 PUBLICITY: ISSUED N (44) | DESCRIPTION (45) N/A

NRC USE ONLY

NAME OF PREPARER J. McGowen PHONE: (815) 942-2920 x549

8304220191 830414
PDR ADOCK 05000237
S PDR

Commonwealth Edison

DEVIATION REPORT

DVR NO. 12 - 2/3 - 83 - 46
STA UNIT YEAR NO.

PART 1 TITLE OF DEVIATION

U-2/3 Diesel Generator Inoperable

OCCURRED 3/21/83 DATE 1320 TIME

SYSTEM AFFECTED 6600 (D/G)

PLANT STATUS AT TIME OF EVENT MODE U-2 S/D U-3 Run, PWR(MWT) 2506, LOAD(MWE) 825

TESTING ☐ YES ☒ NO

DESCRIPTION OF EVENT

Continuous lube oil pump failed on U-2/3 D/G - Initiated required surveillance on U-3.

10 CFR50.72 NRC RED PHONE NOTIFICATION MADE ☐ YES ☒ NO

EQUIPMENT FAILURE ☒ YES ☐ NO WORK REQUEST NO. D26593

RESPONSIBLE SUPERVISOR Bob Herbert DATE 3/21/83

PART 2 OPERATING ENGINEER'S COMMENTS

The Unit 2/3 diesel generator was taken out-of-service and repair of the continuous lube oil pump initiated. All required surveillances were successfully completed.

☐ EVENT OF PUBLIC INTEREST

☐ TECH. SPEC. VIOLATION

☐ NON REPORTABLE OCCURRENCE

☐ 14 DAY REPORTABLE/T.S.

☒ 30 DAY REPORTABLE/T.S. 6.6.B.2.b

☐ ANNUAL/SPECIAL REPORT REQ'D

A.I.R. #

L.E.R. # 83-21/03L-0

☐ 24-HOUR NRC NOTIFICATION REQ'D

(Courtesy) TELEPH Tom Tongue REGION III DATE 3/21/83 TIME 1400

TELEGM/TELECOPY N/A REGION III DATE TIME

☐ CECo CORPORATE NOTIFICATION MADE IF ABOVE NOTIFICATION IS PER 10CFR21

☐ 5-DAY WRITTEN REPORT REQ'D PER 10CFR21

Telecopy ~~TELEPH~~ Dennis P. Galle CECo CORPORATE OFFICER DATE 3-23-83 TIME 1245

PRELIMINARY REPORT COMPLETED AND REVIEWED T.A. Ciesla OPERATING ENGINEER DATE 3/22/83

INVESTIGATED REPORT & RESOLUTION ACCEPTED BY STATION REVIEW J. Brunner 4/14/83 T. A. Ciesla 4/14/83

RESOLUTION APPROVED AND AUTHORIZED FOR DISTRIBUTION Douglas Dunn STATION SUPERINTENDENT DATE 4/15/83

86-5176 (FORM 15-52-1) 10-81