LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 | N Y I P S 2 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | (5)
8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

N'T
1 | REPORT SOURCE L (6) | 0 5 0 0 0 2 4 7 (7) | 0 4 0 1 8 3 (8) | 0 5 0 1 8 3 (9)
8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

2 | During normal operation Service Water Pump No. 25 was declared inoperable when the
3 | pump could not be restarted after a pump trip. Pump 25 was one of the three pumps
4 | assigned to the designated essential header in accordance with T.S.3.3.F.1. The
5 | redundant service water header was established as the essential header within the
6 | time allowed by T.S.3.3.F.2. The health and safety of the public were unaffected.
7 | There have been no similar events.
8 | 9 80

9 | SYSTEM CODE W A (11) | CAUSE CODE E (12) | CAUSE SUBCODE B (13) | COMPONENT CODE P U M P X X (14) | COMP. SUBCODE B (15) | VALVE SUBCODE Z (16)
8 9 10 11 12 13 18 19 20

(17) LER/RO REPORT NUMBER: EVENT YEAR 8 3 | — | SEQUENTIAL REPORT NO. 0 1 0 | / | OCCURRENCE CODE 0 3 | REPORT TYPE L | — | REVISION NO. 0
21 22 23 24 26 27 28 29 30 31 32

ACTION TAKEN B (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0 0 0 0 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. Y (24) | PRIME COMP. SUPPLIER N (25) | COMPONENT MANUFACTURER L 0 1 5 (26)
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

0 | Pump No. 25 was removed and the inspection revealed nylon rope from an old cathodic
1 | protection system in the travelling screens wrapped around the impeller and shaft.
2 | The pump and motor assembly was replaced with a rebuilt spare. The pump was
3 | satisfactorily tested and returned to service. Manufacturer: Layne Bowler Pump Co.
4 | Vertiline Model 300SW16F3.
8 9 80

5 | FACILITY STATUS E (28) | % POWER 1 0 0 (29) | OTHER STATUS NA | METHOD OF DISCOVERY (30) A (31) | DISCOVERY DESCRIPTION (32) Pump Trip
8 9 10 12 13 44 45 46 80

6 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA
8 9 10 11 44 45 80

PERSONNEL EXPOSURES
7 | NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) NA
8 9 11 12 13 80

PERSONNEL INJURIES
8 | NUMBER 0 0 0 (40) | DESCRIPTION (41) NA
8 9 11 12 80

LOSS OF OR DAMAGE TO FACILITY (43)
9 | TYPE Z (42) | DESCRIPTION NA
8 9 10 80

8305160025 830501
PDR ADOCK 05000247
S PDR

PUBLICITY
0 | ISSUED N (44) | DESCRIPTION (45) NA
8 9 10 68 69 80 NRC USE ONLY

NAME OF PREPARER Gary Hinrichs PHONE 914-526-5543