BOSTON EDISON
Pilgrim Nuclear Power Station
Rocky Hill Road
Plymouth, Massachusetts 02360

July 22, 1991
BECo Ltr. 91-93

R. A. Anderson
Vice President &
Station Director
Nuclear Operations

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D.C. 20555

Docket No. 50-293
License No. DPR-35

Subject: Secondary Containment Leak Rate Test Reports

Dear Sir:

A Secondary Containment Leak Rate Test was satisfactorily performed on May 5, 1991 prior to RFO 8 fuel offload. A second Secondary Containment Leak Rate Test was satisfactorily performed on June 20, 1991 prior to RFO 8 fuel reload. Each test verified Secondary Containment integrity as defined by PNPS Technical Specification (TS) 4.7.C.1. The attachments report the test results as required by T.S. 6.9.C.3, Table 6.9.1.a.

R. A. Anderson

WJM/bal

Attachments:

1. Secondary Containment Leak Rate Test 5/5/91
2. Secondary Containment Leak Rate Test 6/20/91

cc: Mr. Thomas T. Martin
Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
475 Allendale Rd.
King of Prussia, PA 19406

Mr. R. B. Eaton
Division of Reactor Projects I/II
Office of NRR - USNRC
One White Flint North - Mail Stop 14D1
11555 Rockville Pike
Rockville, MD 20852

Sr. NRC Resident Inspector - Pilgrim Station

Standard BECo LER Distribution

A017
1/1

230084

9107290187 910722
PDR ADOCK 05000293
P PDR