Southern California Edison Company

P. O. BOX 128

SAN CLEMENTE, CALIFORNIA 92674-0128

R. W. KRIEGER
VICE PRESIDENT
NUCLEAR GENERATION

TELEPHONE
714-368-6255

May 8, 1995

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, D. C. 20555

Subject: Docket No. 50-361
Licensee Event Report No. 95-005
San Onofre Nuclear Generating Station, Unit 2

This submittal provides a voluntary written Licensee Event Report (LER) for an event involving a reduction of pressurizer level due to a valve alignment error. Neither the health nor the safety of plant personnel or the public was affected by this occurrence.

Sincerely,

Enclosure: LER No. 95-005

cc: L. J. Callan, Regional Administrator, NRC Region IV
J. Dyer, Director, Division of Reactor Projects, NRC Region IV
K. E. Perkins, Jr., Director, USNRC Region IV Walnut Creek Field Office
J. Sloan, USNRC Senior Resident Inspector, Units 1, 2 and 3
M. B. Fields, NRC Project Manager, San Onofre Units 2 & 3
Institute of Nuclear Power Operations (INPO)

9505150181 950508
PDR ADOCK 05000361
S PDR

IE22
1/1