Southern California Edison Company

P. O. BOX 128

SAN CLEMENTE, CALIFORNIA 92674-0128

R. W. KRIEGER
VICE PRESIDENT
NUCLEAR GENERATION

TELEPHONE
714-368-6255

May 8, 1995

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Subject: Docket No. 50-361
30-Day Report
Licensee Event Report No. 95-006
San Onofre Nuclear Generating Station, Unit 2

Pursuant to 10 CFR 50.73(d), this submittal provides the required 30-day written Licensee Event Report (LER) for an occurrence involving the reactor coolant system dissolved oxygen being out of specification. Neither the health nor the safety of plant personnel or the public was affected by this occurrence or condition.

If you require any additional information, please so advise.

Sincerely,

RWKrieger

Enclosure: LER No. 95-006

cc: L. J. Callan, Regional Administrator, NRC Region IV
J. Dyer, Director, Division of Reactor Projects, NRC Region IV
K. E. Perkins, Jr., Director, USNRC Region IV Walnut Creek Field Office
J. Sloan, USNRC Senior Resident Inspector, Units 1, 2 and 3
M. B. Fields, NRC Project Manager, San Onofre Units 2 & 3
Institute of Nuclear Power Operations (INPO)

9505150185 950508
PDR ADOCK 05000361
S PDR

IE22
1/1