Southern California Edison Company

P. O. BOX 128

SAN CLEMENTE, CALIFORNIA 92674-0128

R. W. KRIEGER
VICE PRESIDENT
NUCLEAR GENERATION

TELEPHONE
714-368-6255

May 26, 1995

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Subject: Docket Nos. 50-361 and 50-362
Voluntary Report
Licensee Event Report No. 95-007
San Onofre Nuclear Generating Station, Units 2 and 3

This submittal provides a voluntary report for an occurrence involving incorrect rod shadowing factors in the Unit 2 and Unit 3 core protection calculators. Since this occurrence involves similar systems, cause, and corrective actions applicable to Units 2 and 3, a single report for Unit 2 is being submitted in accordance with NUREG-1022. Neither the health nor the safety of plant personnel or the public was affected by this occurrence.

If you require any additional information, please so advise.

Sincerely,

R W Krieger

Enclosure: LER No. 95-007

cc: L. J. Callan, Regional Administrator, NRC Region IV
A. B. Beach, Director, Division of Reactor Projects, Region IV
K. E. Perkins, Jr., Director, Walnut Creek Field Office, NRC Region IV
J. A. Sloan, NRC Senior Resident Inspector, San Onofre Units 2 & 3
M. B. Fields, NRC Project Manager, San Onofre Units 2 and 3
Institute of Nuclear Power Operations (INPO)

9506070173 950526
PDR ADOCK 05000361
S PDR

IE22
1/1