TWX LOGGING

BETH 008

RECEIVED

USAEC-H&S-GTWN

[illegible] 44

U.S. ATOMIC ENERGY COMM.
TWX UNIT

WU INFOMASTER 1-0063840246 09/03/74

TLX WU TFC WSH

015

TWX 7103280475 USAEC H&S GTWN

50-237

PL015 WA3041(1034)(1-0063840246002)PD 09/03/74 1038

ICS IPMVEIB VN

02076 TDVI MORRIS ILL 59 09-03 838A CDT

PMS J. F. [illegible]

DIRECTORATE OF LICENSING (DL)

US ATOMIC ENERGY COMMISSION

WASHINGTON DC 20545

SUBJECT DPR-19 DRESDEN NUCLEAR POWER STATION UNIT 2 THIS WILL CONFIRM A CONVERSATION WITH F. MAURA OF YOUR OFFICE AT 1300 HOURS 1 SEPTEMBER CONCERNING FAILURE OF 2B CONDENSATE BOOSTER PUMP VENT LINE AT APPROXIMATELY 0600 1 SEPTEMBER 1974. [illegible] TO ISOLATE PUMP TO STOP LEAK NATURALLY SPRAYING REACTOR AND SECURED CONDENSATE SYSTEM. ALL WATER WAS VERY LOW LEVEL AND ALL WAS CONFINED TO CONDENSATE PUMP ROOM. WATER WAS PUMPED TO RAD WASTE SYSTEM FOR NORMAL PROCESSING.

G S STEPHENSON, SUPERINTENDENT

DRESDEN NUCLEAR POWER STATION

COMMONWEALTH EDISON CO RR1 MORRIS ILL 60450

1045 EDT

8305230195 740906
PDR ADOCK 05000237
S PDR

USAEC-H&S-GTWN

TWX LOGGING COPY SENT REGION III

9270