Southern California Edison Company

P. O. BOX 128

SAN CLEMENTE, CALIFORNIA 92674-0128

R. W. KRIEGER
VICE PRESIDENT
NUCLEAR GENERATION

TELEPHONE
714-368-6255

July 31, 1995

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C. 20555

Subject: Docket No. 50-361
30 Day Report
Licensee Event Report No. 95-012
San Onofre Nuclear Generating Station, Unit 2

This submittal provides a written Licensee Event Report (LER) for the discovery of several Unit 2 Containment air lock door seal tests that did not meet the literal Technical Specification (TS) requirements due to a typograpical error in the TS. Neither the health nor the safety of plant personnel or the public was affected by this occurrence.

Sincerely,

RWKrieger

Enclosure: LER No. 95-012

cc: L. J. Callan, Regional Administrator, NRC Region IV
J. E. Dyer, Director, Division of Reactor Projects, NRC Region IV
K. E. Perkins, Jr., Director, Walnut Creek Field Office, NRC Region IV
J. A. Sloan, NRC Senior Resident Inspector, San Onofre Units 2 & 3
M. B. Fields, NRC Project Manager, San Onofre Units 2 and 3
Institute of Nuclear Power Operations (INPO)

9508090153 950731
PDR ADOCK 05000361
S PDR

IE22
1/1