GULF STATES UTILITIES COMPANY

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704

AREA CODE 409 838-6631

October 18, 1983
RBG-16,180
File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV, Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

RECEIVED
OCT 21 1983

Dear Mr. Collins:

River Bend Station Unit 1
Docket No. 50-458
Final Report/DR-61

Gulf States Utilities Company has completed its investigation of DR-61 concerning the length of the capscrew which holds the starting air valve assembly in the cylinder head of the standby diesel generators and has determined this condition is not reportable under 10CFR50.55(e).

Sincerely,

J. E. Booker

J. E. Booker
Manager-Engineering,
Nuclear Fuels & Licensing
River Bend Nuclear Group

f PSD
JEB/PJD/kt

cc: Director of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

NRC Resident Inspector-Site

8310280011 831018
PDR ADOCK 05000458
S PDR

10
IE-27