GULF STATES UTILITIES COMPANY

RIVER BEND STATION POST OFFICE BOX 220 ST. FRANCISVILLE, LOUISIANA 70775

AREA CODE 504 635-6094 346-8651

September 12, 1985
RBG-22090
File Nos. G9.5, G9.20.8

Mr. Harold R. Denton, Director
Office of Nuclear Reactor Regulation
U.S. Nuclear Regulation Commission
Washington, D.C. 20555

Dear Mr. Denton:

River Bend Station - Unit 1
Docket No. 50-458

This response provides the status of Gulf States Utilities Company justifications for interim operation (JIOs) for which environmental qualification has been completed. The environmental qualification of the following equipment (previously submitted under 10CFR50.49(i)) has been successfully completed.

- SRN No. 211161-6, Rev. 0; Cable Repair Kits
- SRN No. 225220-1, Rev. 0; Standby Gas Treatment System
- SRN No. 242533-1, Rev. 0; Load Centers
- SRN No. 247497-1, Rev. 1; Electrohydraulic Actuators

The attached table is an update reflecting the qualification of this equipment. Your office will be informed as the remaining JIO's for environmental qualification have been completed.

Sincerely,

J. E. Booker

J. E. Booker
Manager-Engineering,
Nuclear Fuels & Licensing
River Bend Nuclear Group

JEB/WJR/RJK/je

Attachment

8509260076 850912
PDR ADOCK 05000458
P PDR

A048
1/1

ATTACHMENT

RBS
ENVIRONMENTAL QUALIFICATION
SUMMARY LISTING OF
JUSTIFICATIONS FOR INTERIM OPERATION (JIO)

SRN NO.	Rev. No.	Description	Schedule Completion	Required Shutdown
211161-6	0	Cable Repair Kits	Completed (1)	N/A
211161-8	1	Raychem Heat-Shrink	September 1985	N/A
211161-10	1	Heat Tracing	November 1985	N/A
225220-1	0	Standby Gas Treatment	Completed (1)	N/A
241242-1	1	Rockbestos Cable	November 1985	N/A
242533-1	0	Load Centers	Completed (1)	N/A
242562-1	0	Motor Control Centers	November 1985	N/A
247250-1	1	Digital Radiation Monitoring	October 1985	N/A
247433-1	4	Flow Detecting Elements	September 1985 (2)	N/A
247497-1	1	Electrohydraulic Actuators	Completed (1)	N/A
247491-3	0	Air Operated Valves	November 1985	No

Notes:

N/A - No new equipment is required to be installed to replace existing equipment (Not Applicable).

(1) - Qualification is complete. The qualification reports have been reviewed for the RBS specific application and were found acceptable. The qualification documentation is available for review.

(2) - revised