LICENSEE EVENT REPORT

CONTROL BLOCK: [ ] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 | G A E I H 2 (2) | 0 0 0 0 0 0 0 0 0 0 0 (3) | 4 1 1 1 1 (4) | (5)
8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T
1 | REPORT SOURCE L (6) | 0 5 0 0 0 3 6 6 (7) | 1 2 0 5 7 8 (8) | 1 2 1 8 7 8 (9)
8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

2 With the reactor in the Run mode, while making a special inspection of 3 hour fire
3 barriers, a manila rope was found through the fire seal of cable tray 2BHA902 in the
4 RPS M.G. Set room. A fire watch was established in the M. G. Set room per Technical
5 Specification 3.7.7. Public health and safety were not affected by this incident.
6
7
8 80
9

SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
A B (11)	A (12)	E (13)	Z Z Z Z Z Z (14)	Z (15)	Z (16)
9 10	11	12	13 18	19	20

(17) LER/RO REPORT NUMBER: EVENT YEAR 7 8 (21 22) — (23) SEQUENTIAL REPORT NO. 0 7 6 (24 26) / (27) OCCURRENCE CODE 0 3 (28 29) REPORT TYPE L (30) — (31) REVISION NO. 0 (32)

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS (22)	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
B (18)	Z (19)	Z (20)	Z (21)	0 0 0 0	N (23)	N (24)	A (25)	C 2 7 5 (26)
33	34	35	36	37 40	41	42	43	44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

0 The violation of the fire seal was caused by Construction personnel having left the
1 rope through the seal to pull future security system cables and failing to remove
2 it when the silicone foam was poured. The rope was removed and the seal repaired
3 as per Maintenance Request 2-78-4983.
4 80

FACILITY STATUS	% POWER	OTHER STATUS (30)	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
B (28)	0 5 5 (29)	NA	C (31)	Special Inspection
9	10 12	13 44	45 46	80

ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)
Z (33)	Z (34)	NA	NA
9	10 11	44	45 80

PERSONNEL EXPOSURES

NUMBER	TYPE	DESCRIPTION (39)
0 0 0 (37)	Z (38)	NA
9 11	12	13 80

PERSONNEL INJURIES

NUMBER	DESCRIPTION (41)
0 0 0 (40)	NA
9 11	12 80

LOSS OF OR DAMAGE TO FACILITY (43)

TYPE	DESCRIPTION
Z (42)	NA
9	10 80

PUBLICITY

ISSUED	DESCRIPTION (45)	NRC USE ONLY
N (44)	NA	
9	10 68	69 80

781227 0329

NAME OF PREPARER R. T. Nix
Superintendent of Maintenance

PHONE: (912) 367-7781