Tier / Group	Randomly Selected K/A	Reason for Rejection
2/1 RO	263000 K5.01	Was unable to write an operationally valid RO level question for selected K/A (Knowledge of the operational implications of the following concepts as they apply to D.C. ELECTRICAL DISTRIBUTION: Hydrogen generation during battery charging). Perry does not have any documents that identify hydrogen generation as a hazard during battery charging. It is implied in training, but not overtly stated. Randomly selected K/A 218000 K5.01
2/2/ RO	204000 K4.05	Was unable to write an operationally valid RO level question for selected K/A (Knowledge of REACTOR WATER CLEANUP SYSTEM design feature(s) and/or interlocks which provide for the following: Double valve isolation from the reactor). Perry does not have any documents that identify any requirement to have double valve isolation from the reactor. Randomly selected K/A 201003 K4.02