Tier / Group	Randomly Selected K/A	Reason for Rejection
1/1 RO	056.AK1.01	K/A oversampling – natural circulation question replaced with K/A AK1.03. Determined using random number generator, while maintaining K/A category total curves normalized.
1/1 RO	065.AA2.08	K/A oversampling – failure modes of air-operated equipment question replaced with K/A AA2.07. Determined using random number generator, while maintaining K/A category total curves normalized.
1/1 RO	000011.EA2.04	K/A not relevant for this EPE; replaced with EA2.05. Determined using random number generator, while maintaining K/A category total curves normalized.
2/1 RO	013.A3.01	K/A oversampling – ESFAS input and logic question sampled with existing ESFAS actuation logic questions. Randomly replaced with A3.02, determined using random number generator, while maintaining K/A category total curves normalized.
2/1 SRO	103.A2.05	Unable to develop an operationally valid, discriminatory exam question for malfunctions regarding emergency containment entries and required procedural actions coherent to 10CFR55.43(b) topics. Resampled and obtained G2.4.41.