



May 24, 2000  
RC-00-0240

Document Control Desk  
U. S. Nuclear Regulatory Commission  
Washington, DC 20555

Gentlemen:

Stephen A. Byrne  
Vice President  
Nuclear Operations  
803.345.4622

Subject: VIRGIL C. SUMMER NUCLEAR STATION  
DOCKET NO. 50/395  
OPERATING LICENSE NO. NPF-12  
SPECIAL REPORT 2000-02

South Carolina Electric and Gas Company is submitting this Special Report pursuant to the requirements of Technical Specification 3.3.3.6 Action a.

On April 17, 2000, at 1936 hours, the reactor building high range area gamma radiation monitor (RM-G18) annunciated a trouble alarm, possibly due to a lightning strike. After extensive troubleshooting, it has been determined that the inoperability is caused by either the detector or cabling located inside the reactor building. The exact cause can not be determined until repairs are made inside the reactor building.

Since the repairs require reactor building entry, repair or replacement of the faulty equipment will not be performed until the fall 2000 refueling outage (RF12).

The redundant channel of reactor building high range area gamma radiation monitoring is operable and serves as the pre-planned alternate method of monitoring until RM-G18 is returned to service.

If you require further information, please contact Mr. Chris Crowley at (803) 345-4409.

Very truly yours,

Stephen A. Byrne

IE22  
Add'l  
Waiver  
R2  
per cy

CAC/SAB/mb

South Carolina Electric & Gas Co  
Virgil C. Summer Nuclear Station  
P. O. Box 88  
Jenkinsville, South Carolina  
29065

803.345.4344  
803.345.5209  
www.scana.com

c: J. L. Skolds  
T. G. Eppink  
R. J. White  
L. A. Reyes  
K. R. Cotton  
NRC Resident Inspector  
J. B. Knotts, Jr.  
INPO Records Center  
RTS (L-00-0087)  
File (818.08)  
DMS (RC-00-0240)