



SINCLAIR RESEARCH, INC.
400 EAST SIBLEY BOULEVARD
HARVEY, ILLINOIS 60426

OFFICE OF THE VICE PRESIDENT

April 27, 1968

-04

Mr. Edmund J. Oparka
U. S. Atomic Energy Commission
Region III, Division of Compliance
799 Roosevelt Road
Glen Ellyn, Illinois 60426

Dear Sir:

In accordance with your letter of April 17, 1968,
we are returning herewith Forms AEC-591, INSPECTION
FINDINGS AND LICENSEE ACKNOWLEDGEMENT.

Yours very truly,

SINCLAIR RESEARCH, INC.

E. J. Martin
E. J. Martin



Enclosures

MAY 3 1968

A/54

INSPECTION FINDINGS AND LICENSEE ACKNOWLEDGMENT

E(1) IL 26

| | |
|---|--|
| 1. LICENSEE Sinclear Research, Incorporated 400 East Sibley Boulevard Harvey, Illinois 60426 | 2. REGIONAL OFFICE U.S. ATOMIC ENERGY COMMISSION REGION III, DIVISION OF COMPLIANCE 730 ROOSEVELT ROAD GLEN ELLYN, ILLINOIS 60137 |
| 3. LICENSE NUMBER(S) 12-00140-04 | 4. DATE OF INSPECTION April 4, 1968 |
| 5. INSPECTION FINDINGS <input type="checkbox"/> A. No item of noncompliance was found. <input checked="" type="checkbox"/> B. Rooms or areas were not properly posted to indicate the presence of a RADIATION AREA. 10 CFR 20.203(b) or 34.42 <input type="checkbox"/> C. Rooms or areas were not properly posted to indicate the presence of a HIGH RADIATION AREA. 10 CFR 20.203(c) (1) or 34.42 <input type="checkbox"/> D. Rooms or areas were not properly posted to indicate the presence of an AIRBORNE RADIOACTIVITY AREA. 10 CFR 20.203(d) <input checked="" type="checkbox"/> E. Rooms or areas were not properly posted to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(e) <input type="checkbox"/> F. Containers were not properly labeled to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(f) (1) or (f) (2) <input type="checkbox"/> G. A current copy of 10 CFR 20, a copy of the license, or a copy of the operating procedures was not properly posted or made available. 10 CFR 20.206(b) <input type="checkbox"/> H. Form AEC-3 was not properly posted. 10 CFR 20.206(c) <input type="checkbox"/> I. Records of the radiation exposure of individuals were not properly maintained. 10 CFR 20.401(a) or 34.33(b) <input type="checkbox"/> J. Records of surveys or disposals were not properly maintained. 10 CFR 20.401(b) or 34.43(d) <input type="checkbox"/> K. Records of receipt, transfer, disposal, export or inventory of licensed material were not properly maintained. 10 CFR 30.51, 40.61 or 70.51 <input checked="" type="checkbox"/> L. Records of leak tests were not maintained as <u>prescribed in your license</u> , or 10 CFR 34.25(c) <input type="checkbox"/> M. Records of inventories were not maintained. 10 CFR 34.26 <input type="checkbox"/> N. Utilization logs were not maintained. 10 CFR 34.27 <div style="text-align: right;"> (AEC Compliance Inspector)</div> | |
| 6. LICENSEE'S ACKNOWLEDGMENT The AEC Compliance Inspector has explained and I understand the items of noncompliance listed above. The items of noncompliance will be corrected within the next 30 days. <div style="display: flex; justify-content: space-between;"><div data-bbox="186 1753 625 1816"><u>April 27, 1968</u> (Date)</div><div data-bbox="690 1648 1477 1816"> (Licensee Representative - Title or Position)</div></div> | |

ORIGINAL: LICENSEE. COPIES: ☐ CO REGION ☐ CO HEADQUARTERS ☐ CO ENFORCEMENT

Mailed 5-6-68