

EDO Principal Correspondence Control

FROM: DUE: 03/07/01 EDO CONTROL: G20010089
DOC DT: 02/20/01
FINAL REPLY:

Representative Sue W. Kelly

TO:

Chairman Meserve

FOR SIGNATURE OF : ** PRI **

CRC NO: 01-0123

Chairman

DESC:

ROUTING:

Request that Indian Point 2 be held at 50% Power
Until Inspection Data is Fully Examined and
Presented to the Public

Travers
Paperiello
Miralgia
Norry
Reiter
Craig
Burns/Cyr
Collins, NRR

DATE: 02/26/01

ASSIGNED TO: CONTACT:

RI

Miller

SPECIAL INSTRUCTIONS OR REMARKS:

**OFFICE OF THE SECRETARY
CORRESPONDENCE CONTROL TICKET**

Date Printed: Feb 23, 2001 16:47

PAPER NUMBER:	LTR-01-0123	LOGGING DATE:	02/23/2001
ACTION OFFICE:	EDO		
AUTHOR:	Sue Kelly		
AFFILIATION:	REP		
ADDRESSEE:	Richard Meserve		
SUBJECT:	Requests that Indian Point 2 be held at 50% power until inspection data is fully examined and presented to the public		
ACTION:	Signature of Chairman		
DISTRIBUTION:	Chairman, RF, OCA to Ack		
LETTER DATE:	02/20/2001		
ACKNOWLEDGED	No		
SPECIAL HANDLING:	Commission Correspondence		
NOTES:			
FILE LOCATION:	ADAMS		
DATE DUE:	03/09/2001	DATE SIGNED:	

EDO --G20010089

SUE W. KELLY
19TH DISTRICT, NEW YORK

COMMITTEE ON
TRANSPORTATION AND INFRASTRUCTURE
SUBCOMMITTEE ON GROUND TRANSPORTATION
SUBCOMMITTEE ON WATER RESOURCES
AND ENVIRONMENT

COMMITTEE ON SMALL BUSINESS
CHAIRMAN, SUBCOMMITTEE ON REGULATORY
REFORM AND PAPERWORK REDUCTION

COMMITTEE ON BANKING AND
FINANCIAL SERVICES
SUBCOMMITTEE ON FINANCIAL INSTITUTIONS
AND CONSUMER CREDIT
SUBCOMMITTEE ON HOUSING AND
COMMUNITY OPPORTUNITY

ASSISTANT MAJORITY WHIP

Congress of the United States
House of Representatives
Washington, DC 20515-3219

PLEASE REPLY TO:
☐ 1122 LONGWORTH HOUSE OFFICE BUILDING
WASHINGTON, DC 20515
(202) 225-5441
☐ 21 OLD MAIN STREET, ROOM #107
FISHKILL, NEW YORK 12524
(845) 897-5200
☐ 116 RADIO CIRCLE DRIVE
MT. KISCO, NEW YORK 10549
(914) 241-6340


February 20, 2001

Chairman Richard A. Meserve
Nuclear Regulatory Commission
Washington, D.C. 20555

Dear Chairman Meserve:

It is my understanding that a leak in a water discharge pipe on one of the main feedwater pumps has caused operators at the Indian Point 2 nuclear power plant to reduce the plant to 50% power. In light of the many problems experienced at the plant both prior and after the restart in January, I request at this time that the NRC take action to ensure that plant power is held at 50% until the data from the comprehensive inspection in January is fully examined and presented to the public.

Sincerely,


Sue W. Kelly
Member of Congress

REC'D BY SEC

23 FEB 01 3: 1