

March 9, 2001

MEMORANDUM TO: Docket File

FROM: Jack N. Donohew, Project Manager for Palo Verde
Project Directorate IV-2 */RA/*
Division of Licensing Project Management
Office of Nuclear Reactor Regulation

SUBJECT: CLARIFICATION OF INFORMATION PROVIDED IN THE APPLICATION
DATED JANUARY 25, 2001, FOR RELIEF REQUESTS 15 AND 16 FOR
PALO VERDE UNITS 1, 2, AND 3 (TAC NOS. MB1091, MB1092, AND
MB1093)

In the letter of January 25, 2001 (102-04523-CDM/SAB/RKB), Arizona Public Service Company (the licensee) submitted relief requests (RRs) 15 and 16 for NRC review. In RR 16, the licensee provided a list of 4 materials in the section on alternate testing. The licensee stated that Code Case N-616 would be applied to bolting made of these 4 materials.

In the attached e-mail dated February 28, 2001, from the licensee, the license clarifies the third material listed in RR 16. There is no bolting material known as SA-286 Grade 660. The correct reference is to A-286, or SA-453, Grade 660.

Docket Nos.: STN 50-528, STN 50-529, and STN 50-530

Attachment: E-mail Dated February 28, 2001

March 9, 2001

MEMORANDUM TO: Docket File

FROM: Jack N. Donohew, Project Manager for Palo Verde
Project Directorate IV-2 **/RA/**
Division of Licensing Project Management
Office of Nuclear Reactor Regulation

SUBJECT: CLARIFICATION OF INFORMATION PROVIDED IN THE APPLICATION
DATED JANUARY 25, 2001, FOR RELIEF REQUESTS 15 AND 16 FOR
PALO VERDE UNITS 1, 2, AND 3 (TAC NOS. MB1091, MB1092, AND
MB1093)

In the letter of January 25, 2001 (102-04523-CDM/SAB/RKB), Arizona Public Service Company (the licensee) submitted relief requests (RRs) 15 and 16 for NRC review. In RR 16, the licensee provided a list of 4 materials in the section on alternate testing. The licensee stated that Code Case N-616 would be applied to bolting made of these 4 materials.

In the attached e-mail dated February 28, 2001, from the licensee, the license clarifies the third material listed in RR 16. There is no bolting material known as SA-286 Grade 660. The correct reference is to A-286, or SA-453, Grade 660.

Docket Nos.: STN 50-528, STN 50-529, and STN 50-530

Attachment: E-mail Dated February 28, 2001

DISTRIBUTION:

Docket File
PUBLIC

ADAMS Accession No. ML010680004

NRR-106

To receive a copy of this document, indicate "C" in the box					
OFFICE	PDIV-2/PM	C	PDIV-2/LA	C	PDIV-2/SC
NAME	JDonohew:sp		MMcAllister		SDembek
DATE	3/ 8 /01		3/8 /01		3/8 /01

OFFICIAL RECORD COPY

E-MAIL DATED FEBRUARY 28, 2001

From: "Brewer, Ronald K(Z98697)" <RBREWER@apsc.com>
To: "jnd@nrc.gov" <jnd@nrc.gov>
Date: Wed, Feb 28, 2001 6:12 PM
Subject: Relief Request No. 16 - Material Specification

Jack,

In discussions with our metallurgical staff, it was determined that the reference to SA-286 presented in the Alternate Testing section of APS' Relief Request No. 16, submitted on January 25, 2001 was a typographical error. The material specification should have been "A-286" which is equivalent to SA-453, Grade 660.

Please contact me if I may be of further assistance.

R. Kirk Brewer
Sr. Licensing Engineer
Arizona Public Service Company
Palo Verde Nuclear Generating Station
Tel: 623-393-5760 Fax: 623-393-5442
Internet Mail: RBREWER@APSC.COM

CC: "Melton, Michael A(Z65498)" <MMELTON@apsc.com>, "B...